Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE10231 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9004047839 **No. :** Technician Mayur Yadav **Technician Mobile** 8411951301 Name : : **Ticket Type :** Complain Date & Time : 09-12-2023 11:46:30 **Vendor Details :** Customer's Mobile 9004047839 Company Anmol Prestige Name : Mishra Name/Client HSG Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 21-07-2021 12:00:00 Expiry Date : Non-Comprehensive Type : **Product Name :** CCTV **Complain** : 1 boundary camera off One boundary camera issue solve Technician **Comment** : Complain Desktop - Apurva Vajaria **Operator** : One boundary camera issue solve **Remark** :

Status History :	Date Time	Technician Nar	ne Status	Remark	Sign
	09-12-2023 03:25:48	MayurYadav	Completed	One boundary camera issue solve	Aft
	09-12-2023 03:25:48	MayurYadav	Completed	One boundary camera issue solve	Alt
	09-12-2023 03:25:48	MayurYadav	Completed	One boundary camera issue solve	Alt
	09-12-2023 03:25:48	MayurYadav	Completed	One boundary camera issue solve	Alt
	09-12-2023 03:25:48	MayurYadav	Completed	One boundary camera issue solve	Ard
	09-12-2023 03:25:48	MayurYadav	Completed	One boundary camera issue solve	App
	09-12-2023 03:25:48	MayurYadav	Completed	One boundary camera issue solve	Ard
	09-12-2023 03:25:48	MayurYadav	Completed	One boundary camera issue solve	Ard
	09-12-2023 11:46:36	MayurYadav	New		-
Previous Complain History :	Date Time	Technician Name	Remark		
	19-12-2023 04:26:58	Atique Salmani	One boundry camera was off harden side so reconnection from camera end working ok and this camera is working on only 6 pair .		
	14-12-2023 02:18:16	Siddhesh Chavan	2 bondery camera no link issue resoved and all camera working oo		