Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE10572							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9004047839						
Technician Name	Ravi Rajbhar		Technician :	Mobile 8080922965			
Ticket Type :	Complain	Date & Time :	17-01-2024	17-01-2024 02:24:11			
Vendor Details :							
Company Name/Client Name :	Anmol Prestige HSG	Customer's Mobile :	9004047839 Nan		Name :	Mishra	
Address:							
Mumbai,,,,Maharashtra							
AMC Details :							
Expiry Date :	21-07-2021 12:00	Type: Non-Comprehensive					
Product Name:	CCTV						
Complain:	Boundary 1 camera off issue and P2 finger print device not working						
Technician Comment :	boundary one cmaera off issue resolved and ok working done						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	boundary one cmaera off issue resolved and ok working done						
Status History:	Date Time	Technician Name	Status	Remark boundary one cmaera off issue resolved and ok working done			Sign
	19-01-2024 12:30:0	04 Ravi Rajbhar	Completed			ıg	dis
	19-01-2024 11:17:3	Ravi Rajbhar	New				-
	18-01-2024 10:18:4	10 Ravi Rajbhar	New				-
Previous Complain History :	Date Time Technician Name Remark						
	05-02-2024 10:55:3	33 Atique Salmani	P2 staircase camera and second is security cabin cameras was off so chek one reconnect and second is recrmping done working ok.				
	08-01-2024 12:07:	P2 parking Refus area camera falty need to check office. after repaired camera installation done					