







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4170																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9004047839																													
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																										
Ticket Type :	Complain	Date & Time :	02-11-2021 10:51:49																											
Vendor Details :																														
Company Name/Client Name :	Anmol Prestige HSG	Customer's Mobile :	9004047839	Name :	Mishra																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	21-07-2021 12:00:00		Type :	Non-Comprehensive																										
Product Name :	CCTV																													
Complain :	lift camera tv issue & p1 camera off issue																													
Technician Comment :	garden and lift boath issue resolved garden reconection and lift tv mode issue now both working ok also boath dvr working ok.																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	garden and lift boath issue resolved garden reconection and lift tv mode issue now both working ok also boath dvr working ok.																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-11-2021 02:51:04</td><td>Atique Salmani</td><td>Completed</td><td>garden and lift boath issue resolved garden reconection and lift tv mode issue now both working ok also boath dvr working ok.</td><td></td></tr><tr><td>02-11-2021 11:31:30</td><td>Atique Salmani</td><td>Completed</td><td>Bhoomi d wing lift camera issue supply changed use I ball supply dvr end and removed dvr end 5 amp suply for lift camera working ok also check hdd ok also check play back supply barcode 000034021/15/09/2021 Completed.</td><td></td></tr><tr><td>02-11-2021 10:52:22</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>02-11-2021 10:51:49</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-11-2021 02:51:04	Atique Salmani	Completed	garden and lift boath issue resolved garden reconection and lift tv mode issue now both working ok also boath dvr working ok.		02-11-2021 11:31:30	Atique Salmani	Completed	Bhoomi d wing lift camera issue supply changed use I ball supply dvr end and removed dvr end 5 amp suply for lift camera working ok also check hdd ok also check play back supply barcode 000034021/15/09/2021 Completed.		02-11-2021 10:52:22	Atique Salmani	New		-	02-11-2021 10:51:49	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
02-11-2021 02:51:04	Atique Salmani	Completed	garden and lift boath issue resolved garden reconection and lift tv mode issue now both working ok also boath dvr working ok.																											
02-11-2021 11:31:30	Atique Salmani	Completed	Bhoomi d wing lift camera issue supply changed use I ball supply dvr end and removed dvr end 5 amp suply for lift camera working ok also check hdd ok also check play back supply barcode 000034021/15/09/2021 Completed.																											
02-11-2021 10:52:22	Atique Salmani	New		-																										
02-11-2021 10:51:49	Atique Salmani	New		-																										

Previous Complain History :			
	Date Time	Technician Name	Remark
	14-02-2022 04:45:47	Ravi Rajbhar	one bullatt camera stand by install gruond floor parking side and one power supply install stand by to camera canfrm to Apurva sir old camera remove and return office
	08-02-2022 04:14:02	Siddhesh Chavan	3 camera no video issue resolved and one camera siwp and under observation and lift camera no video issue resolved and recotion and date time set