




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6940																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9004047839																			
Technician Name :	Mayur Yadav		Technician Mobile :	8411951301																
Ticket Type :	Complain	Date & Time :	25-11-2022 04:03:09																	
Vendor Details :																				
Company Name/Client Name :	Anmol Prestige HSG	Customer's Mobile :	9004047839	Name :	Mishra															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	21-07-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	Service lift and customer lift camera on off issue and some cameras no link issue																			
Technician Comment :	camera on off issue solve in bms room switch between two switch cable interchange from master switch (in witch 3 NVR connect) to second switch 1. camera cable 86 with uplink 2. camera cable 42 with uplink (yellow tape)																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	camera on off issue solve in bms room switch between two switch cable interchange from master switch (in witch 3 NVR connect) to second switch 1. camera cable 86 with uplink 2. camera cable 42 with uplink (yellow tape)																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-11-2022 06:17:10</td><td>MayurYadav</td><td>Completed</td><td>camera on off issue solve in bms room switch between two switch cable interchange from master switch (in witch 3 NVR connect) to second switch 1. camera cable 86 with uplink 2. camera cable 42 with uplink (yellow tape)</td><td></td></tr><tr><td>25-11-2022 04:03:23</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-11-2022 06:17:10	MayurYadav	Completed	camera on off issue solve in bms room switch between two switch cable interchange from master switch (in witch 3 NVR connect) to second switch 1. camera cable 86 with uplink 2. camera cable 42 with uplink (yellow tape)		25-11-2022 04:03:23	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																
25-11-2022 06:17:10	MayurYadav	Completed	camera on off issue solve in bms room switch between two switch cable interchange from master switch (in witch 3 NVR connect) to second switch 1. camera cable 86 with uplink 2. camera cable 42 with uplink (yellow tape)																	
25-11-2022 04:03:23	MayurYadav	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>30-11-2022 12:57:27</td><td>MayurYadav</td><td>fanc boundary 7 camera started no IPC connector use and box P2 lift camera working ok</td></tr><tr><td>22-11-2022 10:33:37</td><td>Ravi Rajbhar</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	30-11-2022 12:57:27	MayurYadav	fanc boundary 7 camera started no IPC connector use and box P2 lift camera working ok	22-11-2022 10:33:37	Ravi Rajbhar							
Date Time	Technician Name	Remark																		
30-11-2022 12:57:27	MayurYadav	fanc boundary 7 camera started no IPC connector use and box P2 lift camera working ok																		
22-11-2022 10:33:37	Ravi Rajbhar																			