

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7327																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9004047839																			
Technician Name :	Munna Gupta		Technician Mobile :	8080922982																
Ticket Type :	Complain	Date & Time :	10-01-2023 11:36:27																	
Vendor Details :																				
Company Name/Client Name :	Anmol Prestige HSG	Customer's Mobile :	9004047839	Name :	Mishra															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	21-07-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	Service Lift 2 cameras off issue																			
Technician Comment :	service lift camera uplink network disconnected tha switch ke andar. FIR Maine aplin cable ko nikal kar Dala to uplink a Gaya. aur service lift ke camere working Ho Gaye. all camera working properly no any complain.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	service lift camera uplink network disconnected tha switch ke andar. FIR Maine aplin cable ko nikal kar Dala to uplink a Gaya. aur service lift ke camere working Ho Gaye. all camera working properly no any complain.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-01-2023 12:52:14</td><td>Munna Gupta</td><td>Completed</td><td>service lift camera uplink network disconnected tha switch ke andar. FIR Maine aplin cable ko nikal kar Dala to uplink a Gaya. aur service lift ke camere working Ho Gaye. all camera working properly no any complain.</td><td></td></tr><tr><td>10-01-2023 11:36:55</td><td>Munna Gupta</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-01-2023 12:52:14	Munna Gupta	Completed	service lift camera uplink network disconnected tha switch ke andar. FIR Maine aplin cable ko nikal kar Dala to uplink a Gaya. aur service lift ke camere working Ho Gaye. all camera working properly no any complain.		10-01-2023 11:36:55	Munna Gupta	New		-
Date Time	Technician Name	Status	Remark	Sign																
10-01-2023 12:52:14	Munna Gupta	Completed	service lift camera uplink network disconnected tha switch ke andar. FIR Maine aplin cable ko nikal kar Dala to uplink a Gaya. aur service lift ke camere working Ho Gaye. all camera working properly no any complain.																	
10-01-2023 11:36:55	Munna Gupta	New		-																

Previous Complain History :	Date Time	Technician Name	Remark
	07-01-2023 05:07:40	MayurYadav	Finger and face add in P2 device
	05-01-2023 06:06:44	Munna Gupta	HDMI extender 5V power adaptor issue. yadi yah complaint dobara aata hai to technician ke sath mein 5v ka power adaptor sath mein dekar bhejna. abhi Maine temporary dusre extender HDMI ka adaptor change karke chalu kar diya hai. yah complain under observation hai. All cctv system working properly ??.