




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE7402</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9004047839																			
<b>Technician Name :</b>	Chandan Yadav		<b>Technician Mobile :</b>	9833262842																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	18-01-2023 02:05:09																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Anmol Prestige HSG	Customer's Mobile :	9004047839	Name :	Mishra															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	21-07-2021 12:00:00		Type :	Non-Comprehensive																
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	Security cabin tv no signal issue																			
<b>Technician Comment :</b>	TV no single iessu solve change the rj 45 connecter. One tv resolution problem and working done. One camera lance clean.																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	TV no single iessu solve change the rj 45 connecter. One tv resolution problem and working done. One camera lance clean.																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>18-01-2023 02:12:11</td><td>ChandanYadav</td><td>Completed</td><td>TV no single iessu solve change the rj 45 connecter. One tv resolution problem and working done. One camera lance clean.</td><td></td></tr><tr><td>18-01-2023 02:05:21</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	18-01-2023 02:12:11	ChandanYadav	Completed	TV no single iessu solve change the rj 45 connecter. One tv resolution problem and working done. One camera lance clean.		18-01-2023 02:05:21	ChandanYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																
18-01-2023 02:12:11	ChandanYadav	Completed	TV no single iessu solve change the rj 45 connecter. One tv resolution problem and working done. One camera lance clean.																	
18-01-2023 02:05:21	ChandanYadav	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>01-02-2023 01:41:30</td><td>Siddhesh Chavan</td><td>club House camera no video issue resolved switch side camera contion disconnect and reconnect camera and camera working ok</td></tr><tr><td>27-01-2023 01:39:43</td><td>Prashant Nikalje</td><td>prashant visited ste 27.01.2022 2 camera off issued resolved reconnected rj45 connector auto switch camera setting off 1 camera p1 lobby angle setting done</td></tr></tbody></table>					Date Time	Technician Name	Remark	01-02-2023 01:41:30	Siddhesh Chavan	club House camera no video issue resolved switch side camera contion disconnect and reconnect camera and camera working ok	27-01-2023 01:39:43	Prashant Nikalje	prashant visited ste 27.01.2022 2 camera off issued resolved reconnected rj45 connector auto switch camera setting off 1 camera p1 lobby angle setting done						
Date Time	Technician Name	Remark																		
01-02-2023 01:41:30	Siddhesh Chavan	club House camera no video issue resolved switch side camera contion disconnect and reconnect camera and camera working ok																		
27-01-2023 01:39:43	Prashant Nikalje	prashant visited ste 27.01.2022 2 camera off issued resolved reconnected rj45 connector auto switch camera setting off 1 camera p1 lobby angle setting done																		