




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE7603</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9004047839																			
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	10-02-2023 03:16:41																	
<b>Vendor Details :</b>																				
<b>Company Name/Client Name :</b>	Anmol Prestige HSG	<b>Customer's Mobile :</b>	9004047839	<b>Name :</b>	Mishra															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
<b>Expiry Date :</b>	21-07-2021 12:00:00		<b>Type :</b>	Non-Comprehensive																
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	2 cameras of side boundary are closed at night																			
<b>Technician Comment :</b>	2 camera no video issue resolved poe switch side camera cable disconnect and reconnect cable and camera video issue resolved																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	2 camera no video issue resolved poe switch side camera cable disconnect and reconnect cable and camera video issue resolved																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-02-2023 05:36:52</td><td>Siddhesh Chavan</td><td>Completed</td><td>2 camera no video issue resolved poe switch side camera cable disconnect and reconnect cable and camera video issue resolved</td><td></td></tr><tr><td>10-02-2023 03:16:50</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-02-2023 05:36:52	Siddhesh Chavan	Completed	2 camera no video issue resolved poe switch side camera cable disconnect and reconnect cable and camera video issue resolved		10-02-2023 03:16:50	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																
10-02-2023 05:36:52	Siddhesh Chavan	Completed	2 camera no video issue resolved poe switch side camera cable disconnect and reconnect cable and camera video issue resolved																	
10-02-2023 03:16:50	Siddhesh Chavan	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>15-02-2023 10:27:06</td><td>Ravi Rajbhar</td><td>Boundary two camera no video issue resolved and ok working done but one camera under observation camera ip 192.168.1.87</td></tr><tr><td>13-02-2023 11:13:19</td><td>Ravi Rajbhar</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	15-02-2023 10:27:06	Ravi Rajbhar	Boundary two camera no video issue resolved and ok working done but one camera under observation camera ip 192.168.1.87	13-02-2023 11:13:19	Ravi Rajbhar							
Date Time	Technician Name	Remark																		
15-02-2023 10:27:06	Ravi Rajbhar	Boundary two camera no video issue resolved and ok working done but one camera under observation camera ip 192.168.1.87																		
13-02-2023 11:13:19	Ravi Rajbhar																			