Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 Support : | **W** : www.vallabhenterprises.com **E** : vallabhsecure@yahoo.co.in

Service Status Details : VE7613 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9004047839 **No. : Technician** Ravi Rajbhar **Technician Mobile** 8080922965 Name : Complain 11-02-2023 04:40:06 **Ticket Type :** Date & Time : **Vendor Details :** Anmol Prestige Customer's Mobile 9004047839 Company Name : Mishra Name/Client HSG Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 21-07-2021 12:00:00 Expiry Date : Type : Non-Comprehensive **Product Name :** CCTV **Complain**: Ground lobby tV is off since night Lobby cctv camera viewing issue resolved check Lobby site extender adapter faulty Faulty **Technician** adapter hondover vinod sir change adapter then ok working done lobby tv viewing ok Adapter **Comment**: install to client on store BMS room available Confirm to vinod sir Complain Desktop - Apurva Vajaria **Operator** : Lobby cctv camera viewing issue resolved check Lobby site extender adapter faulty Faulty **Remark** : adapter hondover vinod sir change adapter then ok working done lobby tv viewing ok Adapter install to client on store BMS room available Confirm to vinod sir **Status History :** Technician **Date Time** Status Remark Sign Name 11-02-2023 Ravi Rajbhar Completed Lobby cctv camera viewing issue 05:48:33 resolved check Lobby site extender adapter faulty Faulty adapter hondover vinod sir change adapter then ok working done lobby tv viewing ok Adapter install to client on store BMS room available Confirm to vinod sir 11-02-2023 Ravi Rajbhar New 04:40:20 Previous **Date Time Technician Name** Remark Complain 15-02-2023 10:27:06 Ravi Rajbhar Boundary two camera no video issue resolved and ok working **History** : done but one camera under observation camera ip 192.168.1.87 13-02-2023 11:13:19 Ravi Rajbhar