Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE8436 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9004047839 **No. : Technician Name Technician Mobile** 8411951301 Mayur Yadav Complain 27-05-2023 10:12:48 **Ticket Type : Date & Time :** Vendor Details : Customer's Mobile 9004047839 Company Anmol Prestige Name : Mishra Name/Client Name HSG Address : Mumbai,,,, Maharashtra **AMC Details :** 21-07-2021 12:00:00 Expiry Date : Type : Non-Comprehensive **Product Name :** CCTV **Complain**: Security cabin tv repaired uSB Extender need to install USB extender install Ground floor lock alignment problem solve Fencing camera no video issue Technician **Comment**: solve Complain Desktop - Apurva Vajaria **Operator** : **Remark** : USB extender install Ground floor lock alignment problem solve Fencing camera no video issue solve **Status History : Date Time Technician Name** Status Remark Sign 27-05-2023 10:49:58 MayurYadav Completed USB extender install Ground floor lock alignment problem solve Fencing camera no video issue solve 27-05-2023 10:12:59 MayurYadav New **Previous Technician Name Date Time** Remark **Complain History** 09-06-2023 05:09:53 Atique Salmani Already working ok before visit but check n swap Poe switch port camera working ok And also lobby monitor viewing issue resolved 09-06-2023 10:47:05 Atique Salmani One D4 camera issue resolved recrimping from camera end and working ok and on under observation.