## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status De	etails : VE8791						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9004047839						
Technician Name :	Siddhesh Chavan		Technici	nician Mobile 8080922985			
Ticket Type :	Complain	Date & Time:	10-07-20	23 03:06:47	-		
Vendor Details :			-				
Company Name/Client Name :	Anmol Prestige HSG	Customer's Mobile :	9004047839		Name :	Mishra	
Address:							
Mumbai , , , , Ma	harashtra						
AMC Details :							
Expiry Date :	21-07-2021 12:00:	00	Type:		Non-Comprehensive		
<b>Product Name:</b>	CCTV						
Complain:	Cameras need to swipe and boundary 2 cameras off issue and lobby tv not working						
Technician Comment :	society office camera swipe to main gate above security up side camera and nvr side audio off done and society office camera recoding delete apurval by Mishra sir and lobby TV issue resoved ane all camera working OK						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	society office camera swipe to main gate above security up side camera and nvr side audio off done and society office camera recoding delete apurval by Mishra sir and lobby TV issue resoved ane all camera working OK						
<b>Status History</b> :	Date Time	Technician Name	Status	Remark		Sign	
	10-07-2023 04:20:51	Siddhesh Chavan	Completed	society office camera swipe to main gate above security up side camera and nvr side audio off done and society office camera recoding delete apurval by Mishra sir and lobby TV issue resoved ane all camera working OK			
	10-07-2023 03:07:18	Siddhesh Chavan	New	-		-	
Previous Complain History :	Date Time	Date Time Technician Name		Remark			
	08-08-2023 10:23:20	Atique Salmani	adaptor wo	Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .		rack extension	
	05-08-2023 02:08:47	Ravi Rajbhar	working do	boundry side one camera no video issue resloved and ok working done camera side recriping then ok working lobby tv viewing Issue resloved			