

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE9610																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9004047839																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	23-09-2023 11:18:38																	
Vendor Details :																				
Company Name/Client Name :	Anmol Prestige HSG	Customer's Mobile :	9004047839	Name :	Mishra															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	21-07-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	lobby area repaired extender need to install and standby need to collect																			
Technician Comment :	Lobby hdmi extender installed and boundry one camera issue resolved by restart Poe swich working ok.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Lobby hdmi extender installed and boundry one camera issue resolved by restart Poe swich working ok.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>23-09-2023 01:47:08</td><td>Atique Salmani</td><td>Completed</td><td>Lobby hdmi extender installed and boundry one camera issue resolved by restart Poe swich working ok.</td><td></td></tr><tr><td>23-09-2023 11:19:38</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	23-09-2023 01:47:08	Atique Salmani	Completed	Lobby hdmi extender installed and boundry one camera issue resolved by restart Poe swich working ok.		23-09-2023 11:19:38	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
23-09-2023 01:47:08	Atique Salmani	Completed	Lobby hdmi extender installed and boundry one camera issue resolved by restart Poe swich working ok.																	
23-09-2023 11:19:38	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>25-09-2023 03:14:29</td><td>Ravi Rajbhar</td><td>boundry 3 camera no video issue resloved and ok working done only poe switch side cable diconnectat and connect then ok working done</td></tr><tr><td>20-09-2023 12:22:10</td><td>Ravi Rajbhar</td><td>boundry camera no video issue resloved and ok working done poe switch side check cable remove and pluning</td></tr></tbody></table>					Date Time	Technician Name	Remark	25-09-2023 03:14:29	Ravi Rajbhar	boundry 3 camera no video issue resloved and ok working done only poe switch side cable diconnectat and connect then ok working done	20-09-2023 12:22:10	Ravi Rajbhar	boundry camera no video issue resloved and ok working done poe switch side check cable remove and pluning						
Date Time	Technician Name	Remark																		
25-09-2023 03:14:29	Ravi Rajbhar	boundry 3 camera no video issue resloved and ok working done only poe switch side cable diconnectat and connect then ok working done																		
20-09-2023 12:22:10	Ravi Rajbhar	boundry camera no video issue resloved and ok working done poe switch side check cable remove and pluning																		