Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE12816								
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	9820680808							
Technician Name	Atique Salmani		Technic:	nician Mobile 8080922984				
Ticket Type:	New Installation Date & Time :		27-09-20	27-09-2024 11:43:24				
Vendor Details :								
Company Name/Client Name :	Mrudula Chheda	Customer's Mobil:	e 9820680			Mrudi Madan	frudula adam	
Address:								
Mumbai , , , , Maharashtra								
AMC Details:								
Expiry Date :	01-01-1970 05:30:0	Type:	Type:					
Product Name:	VDP							
Complain:	New VDP and supply for lock need to install							
Technician Comment :	Out door camera installation done and also opning from 1st floor ulba vdp with strip lock working ok. Also used 12 volt smps For door lock . Also received payment.							
Complain Operator :	Desktop - Apurva Vajaria							
Remark:	Out door camera installation done and also opning from 1st floor ulba vdp with strip lock working ok. Also used 12 volt smps For door lock . Also received payment.							
Status History:	Date Time	Technician Name	Status	R	lemark		Sign	
	27-09-2024 06:00:53	Atique Salmani	Completed	done and also floor ulba vdj		2	St.	
	27-09-2024 11:43:30	Atique Salmani	New			-		
Previous	Date Time	Technician Name		Remark				
Complain History :	20-09-2024 12:32:27	Siddhesh Chavan		Need to Change 1st floor vdp and ground floor lock power supply and out door Camera and install power point				