




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE629																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	8291652468																																		
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																															
Ticket Type :	Complain	Date & Time :	06-11-2019 05:31:56																																
Vendor Details :																																			
Company Name/Client Name :	Mukta A2 Cinemas Ltd	Customer's Mobile :	8291652468	Name :	Mukta Suncity																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	CCTV																																		
Complain :	ground floor and 4th floor camera off																																		
Technician Comment :	grond floor store room issue resolved and 4th floor painding due to wire break.																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	grond floor store room issue resolved and 4th floor painding due to wire break.																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>15-11-2019 04:47:41</td><td>Atique Salmani</td><td>Completed</td><td></td><td>-</td></tr><tr><td>08-11-2019 03:56:59</td><td>Atique Salmani</td><td>Work Pending</td><td></td><td>-</td></tr><tr><td>07-11-2019 05:54:41</td><td>Atique Salmani</td><td>Completed</td><td>grond floor store room issue resolved and 4th floor painding due to wire break.</td><td></td></tr><tr><td>07-11-2019 10:33:18</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>06-11-2019 05:31:56</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	15-11-2019 04:47:41	Atique Salmani	Completed		-	08-11-2019 03:56:59	Atique Salmani	Work Pending		-	07-11-2019 05:54:41	Atique Salmani	Completed	grond floor store room issue resolved and 4th floor painding due to wire break.		07-11-2019 10:33:18	Atique Salmani	New		-	06-11-2019 05:31:56	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																															
15-11-2019 04:47:41	Atique Salmani	Completed		-																															
08-11-2019 03:56:59	Atique Salmani	Work Pending		-																															
07-11-2019 05:54:41	Atique Salmani	Completed	grond floor store room issue resolved and 4th floor painding due to wire break.																																
07-11-2019 10:33:18	Atique Salmani	New		-																															
06-11-2019 05:31:56	Atique Salmani	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>03-02-2020 03:09:55</td><td>MayurYadav</td><td>software installed in computer license key provide with support from anil and yash bhai</td></tr><tr><td>12-08-2019 01:11:01</td><td>AnilYadav</td><td>3Rd floor camera cable check cable ok but DC pin faulty DC pin change complaint resolve.</td></tr></tbody></table>					Date Time	Technician Name	Remark	03-02-2020 03:09:55	MayurYadav	software installed in computer license key provide with support from anil and yash bhai	12-08-2019 01:11:01	AnilYadav	3Rd floor camera cable check cable ok but DC pin faulty DC pin change complaint resolve.																					
Date Time	Technician Name	Remark																																	
03-02-2020 03:09:55	MayurYadav	software installed in computer license key provide with support from anil and yash bhai																																	
12-08-2019 01:11:01	AnilYadav	3Rd floor camera cable check cable ok but DC pin faulty DC pin change complaint resolve.																																	