Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE3228 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9223207875 **No. : Technician Name Technician Mobile :** 8411951301 Mayur Yadav Complain Date & Time : 12-06-2021 11:16:30 **Ticket Type : Vendor Details :** Shoppers Stop Customer's Mobile 9223207875 Nandu Sir Company Name : Name/Client Name Ltd - HO Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** Ppm **Complain**: Fire ppm done all detector clean 5th floor FAS panel battery problem Technician **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : ppm done all detector clean 5th floor FAS panel battery problem **Status History :** Technician Name **Date Time** Status Remark Sign 26-06-2021 04:15:53 MayurYadav Completed ppm done all detector clean 5th floor FAS panel battery with problem 26-06-2021 10:34:09 MayurYadav New 12-06-2021 11:16:48 MayurYadav New 12-06-2021 11:16:30 MayurYadav New Previous Technician **Date Time** Remark **Complain History** Name : 03-08-2023 Atique Salmani 11 dome 6 fish eye with pole bracket total cameras 17 3rd and 10:55:52 5th boath 6 Poe swich 3nos on third and 3 nos on 5th 32 channel NVR cable approx 550 meter And patil sir required old NVR 3 floor camera in 1 NVR and 5 th floor in 1 NVR 29-07-2023 1- 3rd floor main enterance biometric access divice scaner check Ravi Rajbhar 02:21:56 our side ok working done but nandu sir they said sometimes it doesn't work divice 2- 5th floor it room sarver room em lock issue resloved only mainget paty propely fiting our side