Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE3617 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9223207875 **No. :** Technician Ravi Rajbhar **Technician Mobile :** 8080922965 Name : Complain 12-08-2021 11:22:20 **Ticket Type : Date & Time : Vendor Details :** Company Shoppers Stop Customer's Mobile 9223207875 Name : Nandu Sir Name/Client Ltd - HO Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: camera timing issue both NVR date and dime issue resolved and ok working done infrom to nandu sir and security Technician parson (Patil) and mause faulty need to chenge client side recording also going on in NVR **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : both NVR date and dime issue resolved and ok working done infrom to nandu sir and security parson (Patil) and mause faulty need to chenge client side recording also going on in NVR **Status History : Date Time Technician Name** Status Remark Sign 12-08-2021 Ravi Rajbhar Completed both NVR date and dime issue resolved and ok working done 02:22:51 infrom to nandu sir and security parson (Patil) and mause faulty need to chenge client side recording also going on in NVR 12-08-2021 New Ravi Rajbhar 11:22:38 12-08-2021 Ravi Rajbhar New 11:22:20

Previous Complain History :	Date Time	Technician Name	Remark
instory .		Atique Salmani	11 dome 6 fish eye with pole bracket total cameras 17 3rd and 5th boath 6 Poe swich 3nos on third and 3 nos on 5th 32 channel NVR cable approx 550 meter And patil sir required old NVR 3 floor camera in 1 NVR and 5 th floor in 1 NVR
	29-07-2023 02:21:56	Ravi Rajbhar	1- 3rd floor main enterance biometric access divice scaner check our side ok working done but nandu sir they said sometimes it doesn't work divice 2- 5th floor it room sarver room em lock issue resloved only mainget paty propely fiting our side