




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3653</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9223207875																								
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																					
<b>Ticket Type :</b>	New Installation	<b>Date &amp; Time :</b>	17-08-2021 12:36:07																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Shoppers Stop Ltd - HO	<b>Customer's Mobile :</b>	9223207875	<b>Name :</b>	Nandu Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	Fire																								
<b>Complain :</b>	need to install backup battery																								
<b>Technician Comment :</b>	installed 2 battery in new fire pannel and also old pannel refilled new clip for battery wiring fault now working ok .																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	installed 2 battery in new fire pannel and also old pannel refilled new clip for battery wiring fault now working ok .																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>17-08-2021 01:14:08</td><td>Atique Salmani</td><td>Completed</td><td>installed 2 battery in new fire pannel and also old pannel refilled new clip for battery wiring fault now working ok .</td><td></td></tr><tr><td>17-08-2021 12:36:19</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>17-08-2021 12:36:07</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	17-08-2021 01:14:08	Atique Salmani	Completed	installed 2 battery in new fire pannel and also old pannel refilled new clip for battery wiring fault now working ok .		17-08-2021 12:36:19	Atique Salmani	New		-	17-08-2021 12:36:07	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
17-08-2021 01:14:08	Atique Salmani	Completed	installed 2 battery in new fire pannel and also old pannel refilled new clip for battery wiring fault now working ok .																						
17-08-2021 12:36:19	Atique Salmani	New		-																					
17-08-2021 12:36:07	Atique Salmani	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>03-08-2023 10:55:52</td><td>Atique Salmani</td><td>11 dome 6 fish eye with pole bracket total cameras 17 3rd and 5th boath 6 Poe swich 3nos on third and 3 nos on 5th 32 channel NVR cable approx 550 meter And patil sir required old NVR 3 floor camera in 1 NVR and 5 th floor in 1 NVR</td></tr><tr><td>29-07-2023 02:21:56</td><td>Ravi Rajbhar</td><td>1- 3rd floor main entrance biometric access divice scaner check our side ok working done but nandu sir they said sometimes it doesn't work divice 2- 5th floor it room sarver room em lock issue resloved only mainget paty propely fitting our side</td></tr></tbody></table>					Date Time	Technician Name	Remark	03-08-2023 10:55:52	Atique Salmani	11 dome 6 fish eye with pole bracket total cameras 17 3rd and 5th boath 6 Poe swich 3nos on third and 3 nos on 5th 32 channel NVR cable approx 550 meter And patil sir required old NVR 3 floor camera in 1 NVR and 5 th floor in 1 NVR	29-07-2023 02:21:56	Ravi Rajbhar	1- 3rd floor main entrance biometric access divice scaner check our side ok working done but nandu sir they said sometimes it doesn't work divice 2- 5th floor it room sarver room em lock issue resloved only mainget paty propely fitting our side											
Date Time	Technician Name	Remark																							
03-08-2023 10:55:52	Atique Salmani	11 dome 6 fish eye with pole bracket total cameras 17 3rd and 5th boath 6 Poe swich 3nos on third and 3 nos on 5th 32 channel NVR cable approx 550 meter And patil sir required old NVR 3 floor camera in 1 NVR and 5 th floor in 1 NVR																							
29-07-2023 02:21:56	Ravi Rajbhar	1- 3rd floor main entrance biometric access divice scaner check our side ok working done but nandu sir they said sometimes it doesn't work divice 2- 5th floor it room sarver room em lock issue resloved only mainget paty propely fitting our side																							