## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

E : vallabhsecure@yal	1100.C0.III					
Service Status De	tails : VE8499					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob. No. :	9223207875					
Technician Name :	Atique Salmani		Technic	cian Mobile : 8080922984		4
Ticket Type:	Complain	Date & Time:	05-06-2023 12:25:56			
Vendor Details :	•	_	•			
Company Name/Client Name :	Shoppers Stop Ltd - HO	Customer's Mobile:	le 9223207875		Name:	Nandu Sir
Address:			-			
Mumbai , , , , Ma	harashtra					
AMC Details :						
Expiry Date :	01-01-1970 05:30	:00	Type:			
<b>Product Name:</b>	CCTV					
Complain:	8 cameras off issue					
Technician Comment :	3rd floor reception 2camera Non app room Private brand Tailor room cadd room There issue from NVR end eswich ulink cable rj 45 issue so recrimp from NVR ends working ok all cameras					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	3rd floor reception 2camera Non app room Private brand Tailor room cadd room There issue from NVR end eswich ulink cable rj 45 issue so recrimp from NVR ends working ok all cameras					
Status History :	Date Time	Technician Name	Status	Remark		Sign
	05-06-2023 03:42:22	Atique Salmani	Completed	3rd floor reception 2camera Non app room Private brand Tailor room cadd room There issue from NVR end eswich ulink cable rj 45 issue so recrimp from NVR ends working ok all cameras		ble
	05-06-2023 12:26:02	Atique Salmani	New			-
Previous Complain History :	Date Time	Technician Name	Remark			
	17-06-2023 11:01:54	Ravi Rajbhar	ppm done of fire alarm? 3rd floor 3 rd floor all smoke detectors clean and one smoke detectors no. 53 double show in panal old tailor room then need to change number smoke detectors 94 old tailor room battery fault show - battery missing loop 1 - total divice 91 loop 2 - total divice 78 5th floor 5th floor all smoke detectors clean and ok working done loop 1 - divice 93 loop 2-divice 73 fault show in panal battery waring both panal password -9898			