

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE871																																			
Priority :	High																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9223207875																																		
Technician Name :	Mayur Yadav		Technician Mobile :	8411951301																															
Ticket Type :	New Installation	Date & Time :	07-01-2020 10:45:21																																
Vendor Details :																																			
Company Name/Client Name :	Shoppers Stop Ltd - HO	Customer's Mobile :	9223207875	Name :	Nandu Sir																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	Fire																																		
Complain :	Smoke sensor 8 Nos																																		
Technician Comment :	total 12 detector fault Found																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	total 12 detector fault Found																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>16-01-2021 02:09:27</td><td>MayurYadav</td><td>In Progress</td><td>total 12 detector fault Found</td><td></td></tr><tr><td>16-01-2021 10:29:50</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>14-03-2020 12:29:49</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>24-01-2020 06:15:50</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>07-01-2020 10:45:22</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	16-01-2021 02:09:27	MayurYadav	In Progress	total 12 detector fault Found		16-01-2021 10:29:50	MayurYadav	New		-	14-03-2020 12:29:49	MayurYadav	New		-	24-01-2020 06:15:50	MayurYadav	New		-	07-01-2020 10:45:22	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																															
16-01-2021 02:09:27	MayurYadav	In Progress	total 12 detector fault Found																																
16-01-2021 10:29:50	MayurYadav	New		-																															
14-03-2020 12:29:49	MayurYadav	New		-																															
24-01-2020 06:15:50	MayurYadav	New		-																															
07-01-2020 10:45:22	MayurYadav	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-07-2023 02:21:56</td><td>Ravi Rajbhar</td><td>1- 3rd floor main enterance biometric access divice scaner check our side ok working done but nandu sir they said sometimes it doesn't work divice 2- 5th floor it room sarver room em lock issue resloved only mainget paty propely fiting our side</td></tr><tr><td>29-07-2023 02:19:44</td><td>Ravi Rajbhar</td><td>2nd floor new biometric time attendance divice install with exit switch , 12 volt power supply and bolt lock install but glass door work pending client side user - 3107 pass - 3107</td></tr></tbody></table>					Date Time	Technician Name	Remark	29-07-2023 02:21:56	Ravi Rajbhar	1- 3rd floor main enterance biometric access divice scaner check our side ok working done but nandu sir they said sometimes it doesn't work divice 2- 5th floor it room sarver room em lock issue resloved only mainget paty propely fiting our side	29-07-2023 02:19:44	Ravi Rajbhar	2nd floor new biometric time attendance divice install with exit switch , 12 volt power supply and bolt lock install but glass door work pending client side user - 3107 pass - 3107																					
Date Time	Technician Name	Remark																																	
29-07-2023 02:21:56	Ravi Rajbhar	1- 3rd floor main enterance biometric access divice scaner check our side ok working done but nandu sir they said sometimes it doesn't work divice 2- 5th floor it room sarver room em lock issue resloved only mainget paty propely fiting our side																																	
29-07-2023 02:19:44	Ravi Rajbhar	2nd floor new biometric time attendance divice install with exit switch , 12 volt power supply and bolt lock install but glass door work pending client side user - 3107 pass - 3107																																	