Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE5546 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9821036391 **No. :** Technician Yogesh Desai **Technician Mobile** 8080922963 Name : : Complain Date & Time : 25-05-2022 10:10:43 **Ticket Type :** Vendor Details : Customer's Mobile Company Petit Tower 9821036391 Naozer Name : Name/Client CHS Ltd Baldawala Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** Intercom flat no 1601 no ring issue **Complain**: New phone installed and cash received from client Technician **Comment** : Desktop - Apurva Vajaria Complain **Operator** : **Remark** : New phone installed and cash received from client **Status History : Technician Name Date Time** Status Remark Sign YogeshDesai 31-05-2022 01:38:41 Completed New phone installed and cash received from client YogeshDesai 31-05-2022 10:10:49 New 25-05-2022 01:43:15 YogeshDesai Client Side device faulty need to chenge 25-05-2022 11:05:40 YogeshDesai New 25-05-2022 11:05:27 YogeshDesai New 25-05-2022 11:05:19 YogeshDesai New 25-05-2022 10:10:59 YogeshDesai New 25-05-2022 10:10:43 YogeshDesai New

Previous Complain History :	Date Time	Technician Name	Remark
	25-05-2022 01:11:27	Javed Bhaldar	system level to pravin room junction box main line ok everything working fine but pravin room junction box to main gate loby junction box armald cable folty very distubans in line after main line connect in pravin room junction box
	30-04-2022 02:23:28	Siddhesh Chavan	ppm done and business room pc slow issue need to resolve as soon as possible