

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | **W :** www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7010																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9821036391																								
Technician Name :	Prashant Nikalje	Technician Mobile :	9664609225																						
Ticket Type :	New Installation	Date & Time :	05-12-2022 10:42:36																						
Vendor Details :																									
Company Name/Client Name :	Petit Tower CHS Ltd	Customer's Mobile :	9821036391	Name :	Naozer Baldawala																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00	Type :																							
Product Name :	Time And Attendance																								
Complain :	new Attendance device install																								
Technician Comment :																									
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	1 biomax device install with cabling																								
Status History :	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Status</th> <th>Remark</th> <th>Sign</th> </tr> </thead> <tbody> <tr> <td>12-12-2022 11:34:07</td> <td>Prashant Nikalje</td> <td>Completed</td> <td></td> <td>-</td> </tr> <tr> <td>06-12-2022 10:28:57</td> <td>Prashant Nikalje</td> <td>New</td> <td></td> <td>-</td> </tr> <tr> <td>05-12-2022 10:43:30</td> <td>Prashant Nikalje</td> <td>New</td> <td></td> <td>-</td> </tr> </tbody> </table>					Date Time	Technician Name	Status	Remark	Sign	12-12-2022 11:34:07	Prashant Nikalje	Completed		-	06-12-2022 10:28:57	Prashant Nikalje	New		-	05-12-2022 10:43:30	Prashant Nikalje	New		-
Date Time	Technician Name	Status	Remark	Sign																					
12-12-2022 11:34:07	Prashant Nikalje	Completed		-																					
06-12-2022 10:28:57	Prashant Nikalje	New		-																					
05-12-2022 10:43:30	Prashant Nikalje	New		-																					
Previous Complain History :	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Remark</th> </tr> </thead> <tbody> <tr> <td>05-12-2022 10:41:27</td> <td>Prashant Nikalje</td> <td>25.11.2022 - Prashant/Sonu - 1 new hikvision IP camera install IP dome - 192.168.1.163 - society office outside door admin 1- pass: atia@123 06.12.2022 - Prashant/Dilshad - 1 biomax device install with cabling 14 no. camera cable change and crimping both side RJ45.</td> </tr> <tr> <td>28-11-2022 10:04:37</td> <td>Ravi Rajbhar</td> <td>dvr 1 camera no .6 video issue resolved and camera no.8 cable faulty need to change cable rj6 50- 60 meter aprox LG floor camera ok working check dvr side and camera remove with hondover to society office (sanjay singh) nvr camera no. 14 cable faulty one pair green and two pair cable used to camera old camera ok working done but testing purposes power supply used confrim to falguni mdm and 1502 intercom check cable cut duct in side and infrim to sanjay Singh security parson</td> </tr> </tbody> </table>					Date Time	Technician Name	Remark	05-12-2022 10:41:27	Prashant Nikalje	25.11.2022 - Prashant/Sonu - 1 new hikvision IP camera install IP dome - 192.168.1.163 - society office outside door admin 1- pass: atia@123 06.12.2022 - Prashant/Dilshad - 1 biomax device install with cabling 14 no. camera cable change and crimping both side RJ45.	28-11-2022 10:04:37	Ravi Rajbhar	dvr 1 camera no .6 video issue resolved and camera no.8 cable faulty need to change cable rj6 50- 60 meter aprox LG floor camera ok working check dvr side and camera remove with hondover to society office (sanjay singh) nvr camera no. 14 cable faulty one pair green and two pair cable used to camera old camera ok working done but testing purposes power supply used confrim to falguni mdm and 1502 intercom check cable cut duct in side and infrim to sanjay Singh security parson											
Date Time	Technician Name	Remark																							
05-12-2022 10:41:27	Prashant Nikalje	25.11.2022 - Prashant/Sonu - 1 new hikvision IP camera install IP dome - 192.168.1.163 - society office outside door admin 1- pass: atia@123 06.12.2022 - Prashant/Dilshad - 1 biomax device install with cabling 14 no. camera cable change and crimping both side RJ45.																							
28-11-2022 10:04:37	Ravi Rajbhar	dvr 1 camera no .6 video issue resolved and camera no.8 cable faulty need to change cable rj6 50- 60 meter aprox LG floor camera ok working check dvr side and camera remove with hondover to society office (sanjay singh) nvr camera no. 14 cable faulty one pair green and two pair cable used to camera old camera ok working done but testing purposes power supply used confrim to falguni mdm and 1502 intercom check cable cut duct in side and infrim to sanjay Singh security parson																							