







# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE13536</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9833602788																													
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																										
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	13-12-2024 01:23:39																											
<b>Vendor Details :</b>																														
<b>Company Name/Client Name :</b>	Queens Marys High School - Mira Road	<b>Customer's Mobile :</b>	9833602788	<b>Name :</b>	Narendra Dubey																									
<b>Address :</b>																														
Mumbai , , , , Maharashtra																														
<b>AMC Details :</b>																														
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																											
<b>Product Name :</b>	CCTV																													
<b>Complain :</b>	4th floor and 3rd floor bathroom outside camera need to install																													
<b>Technician Comment :</b>	Two cmaera install 3rd floor toilet side viewing And 4th floor cmaera install And one cmaera ground floor starts And dvr no. 2 recoding starts today under observation going on dvr no.2																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	Two cmaera install 3rd floor toilet side viewing And 4th floor cmaera install And one cmaera ground floor starts And dvr no. 2 recoding starts today under observation going on dvr no.2																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>19-12-2024 01:57:42</td><td>Ravi Rajbhar</td><td>Completed</td><td>Two cmaera install 3rd floor toilet side viewing And 4th floor cmaera install And one cmaera ground floor starts And dvr no. 2 recoding starts today under observation going on dvr no.2</td><td></td></tr><tr><td>19-12-2024 11:07:22</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>13-12-2024 04:16:45</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>2 camera not install.cakble not a proper side.</td><td></td></tr><tr><td>13-12-2024 01:23:59</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	19-12-2024 01:57:42	Ravi Rajbhar	Completed	Two cmaera install 3rd floor toilet side viewing And 4th floor cmaera install And one cmaera ground floor starts And dvr no. 2 recoding starts today under observation going on dvr no.2		19-12-2024 11:07:22	Ravi Rajbhar	New		-	13-12-2024 04:16:45	Ravi Rajbhar	Work Pending	2 camera not install.cakble not a proper side.		13-12-2024 01:23:59	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																										
19-12-2024 01:57:42	Ravi Rajbhar	Completed	Two cmaera install 3rd floor toilet side viewing And 4th floor cmaera install And one cmaera ground floor starts And dvr no. 2 recoding starts today under observation going on dvr no.2																											
19-12-2024 11:07:22	Ravi Rajbhar	New		-																										
13-12-2024 04:16:45	Ravi Rajbhar	Work Pending	2 camera not install.cakble not a proper side.																											
13-12-2024 01:23:59	Ravi Rajbhar	New		-																										

Previous Complain History :	Date Time	Technician Name	Remark
	18-11-2024 01:07:24	ManojPolekar	Cctv ppm done all camera working ok Ground floor 1 DVR power supply changed
	09-08-2024 12:23:02	PravinJagade	Out side canera off issue resolved working done. All camera proper working. Work complete