

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE653																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9769052914																								
Technician Name :		Technician Mobile :																							
Ticket Type :	Complain	Date & Time :	12-11-2019 03:37:50																						
Vendor Details :																									
Company Name/Client Name :	Diyas Enterprise	Customer's Mobile :	9769052914	Name :	Navin Bhai																				
Address :																									
Mumbai , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00	Type :																							
Product Name :	VDP																								
Complain :	need to shift VDP from inside to out side																								
Technician Comment :																									
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :																									
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-01-2020 03:48:14</td><td></td><td>Client Side</td><td></td><td>-</td></tr><tr><td>12-11-2019 03:38:01</td><td></td><td>New</td><td></td><td>-</td></tr><tr><td>12-11-2019 03:37:51</td><td></td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	30-01-2020 03:48:14		Client Side		-	12-11-2019 03:38:01		New		-	12-11-2019 03:37:51		New		-
Date Time	Technician Name	Status	Remark	Sign																					
30-01-2020 03:48:14		Client Side		-																					
12-11-2019 03:38:01		New		-																					
12-11-2019 03:37:51		New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>10-07-2021 10:34:50</td><td>Atique Salmani</td><td>cable continuti check and after find the cable conection done and boath swich working ok supply used there was in spare suplly so use its working ok.</td></tr><tr><td>30-06-2021 11:22:31</td><td>Ravi Rajbhar</td><td>intercom 4 LL line check but 204 /210 port(04/10) issue and 203and /213 line issue resolved and ok working done with cabling check</td></tr></tbody></table>					Date Time	Technician Name	Remark	10-07-2021 10:34:50	Atique Salmani	cable continuti check and after find the cable conection done and boath swich working ok supply used there was in spare suplly so use its working ok.	30-06-2021 11:22:31	Ravi Rajbhar	intercom 4 LL line check but 204 /210 port(04/10) issue and 203and /213 line issue resolved and ok working done with cabling check											
Date Time	Technician Name	Remark																							
10-07-2021 10:34:50	Atique Salmani	cable continuti check and after find the cable conection done and boath swich working ok supply used there was in spare suplly so use its working ok.																							
30-06-2021 11:22:31	Ravi Rajbhar	intercom 4 LL line check but 204 /210 port(04/10) issue and 203and /213 line issue resolved and ok working done with cabling check																							