## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

E: valiabnsecure@yanoo.co.in							
Service Status Details : VE11932							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9702786668						
Technician Name :	Atique Salmani		Technic	cian Mobile : 8080922984			
Ticket Type :	Complain	Date & Time :	19-06-2024 02:42:46				
Vendor Details :							
Company Name/Client Name :	Beam Hospital (Womens Hospital)	Customer's Mobile	970278	6668	Name :	Nazia	
Address:							
Mumbai,,,,Mah	arashtra						
AMC Details :							
Expiry Date :	30-09-2020 12:00:0	Type:	: Comprehensive		re		
<b>Product Name:</b>	CCTV						
Complain:	In mobile cameras offline issue						
Technician Comment :	Mrd room new smoke detectors chenged with base working ok. And online issue resolved ther is changed static IP so report forwarding on mercusus router working ok.						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	Mrd room new smoke detectors chenged with base working ok. And online issue resolved ther is changed static IP so report forwarding on mercusus router working ok.						
<b>Status History:</b>	Date Time	Technician Name	Status	Remark		Sign	
	20-06-2024 05:17:23	Atique Salmani	Completed	Mrd room new smoke detectors chenged with base working ok. And online issue resolved ther is changed static IP so report forwarding on mercusus router working ok.		Roy	
	20-06-2024 01:19:52	Atique Salmani	New			-	
Previous Complain History :	Date Time	Technician Name		Remark			
	30-05-2024 04:37:59	Atique Salmani	3rd floor dahua dvr I line done with crimping working ok And mrd room camera installation done working ok.				
	30-05-2024 10:49:23	Atique Salmani	Ppm completed and 3 floor mandi dahua dvr offline becz lan cable cut by mouse new cabling going on and mrd room smoke detector and camera collect becz faulty.				