Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

| Service Status Details : VE2240 | | | | | | | | |
|----------------------------------|---|---------------------|---------------------|---------------|-------|--|--|--|
| Priority: | High | | | | | | | |
| Created By: | Admin - Apurva Vajaria | | | | | | | |
| Complaint Mob. No. : | 9702786668 | | | | | | | |
| Technician Name : | Atique Salmani | | Technician Mobile : | 8080922984 | | | | |
| Ticket Type: | Complain | Date & Time : | 19-11-2020 04:01:12 | | | | | |
| Vendor Details : | | | | | | | | |
| Company Name/Client Name : | Beam Hospital (Womens Hospital) | Customer's Mobile : | 9702786668 | Name: | Nazia | | | |
| Address: | | | | | | | | |
| Mumbai , , , , Maharashtra | | | | | | | | |
| AMC Details : | | | | | | | | |
| Expiry Date : | 30-09-2020 12:00:00 | | Type: | Comprehensive | | | | |
| Product Name: | Ppm | | | | | | | |
| Complain : | ppm | | | | | | | |
| Technician Comment : | there is coming in zone 2 open loop so check 1st floor 1st detector to second detector power not coming so and wrong conction dobcorrect connection and clean all smoke detector now fire alarm 4 zone working healthy conditions. cctv work painding need tv for reset date n time and also find out 2cameras v loss | | | | | | | |
| Complain Operator : | Desktop - Apurva Vajaria | | | | | | | |
| Remark : | there is coming in zone 2 open loop so check 1st floor 1st detector to second detector power not coming so and wrong conction dobcorrect connection and clean all smoke detector now fire alarm 4 zone working healthy conditions. cctv work painding need tv for reset date n time and also find out 2cameras v loss | | | | | | | |

| Status History : | Date Time | Technician Name | Status | Remark | Sign |
|-----------------------------------|------------------------|-----------------|--|---|--------|
| | 02-02-2021 04:04:13 | Atique Salmani | Work Pending | there is coming in zone 2 open loop so check 1st floor 1st detector to second detector power not coming so and wrong conction dobcorrect connection and clean all smoke detector now fire alarm 4 zone working healthy conditions. cctv work painding need tv for reset date n time and also find out 2cameras v loss | fawa 6 |
| | 02-02-2021 12:16:12 | Atique Salmani | New | | - |
| | 21-01-2021 03:52:34 | Atique Salmani | Client Side | | - |
| | 21-01-2021 03:52:30 | Atique Salmani | Work Pending | | - |
| | 21-01-2021 10:33:59 | Atique Salmani | New | | - |
| | 19-11-2020 04:01:12 | Atique Salmani | New | | - |
| Previous Complain History : | Date Time | Technician Name | Remark | | |
| | 15-07-2023 10:32:24 | Atique Salmani | In Manju mam phone cctv online done working ok. | | |
| | 23-06-2023 10:31:29 | Atique Salmani | All smok detector checked working ok also check by mcps and o.t. door access issue resolved 3rd floor 3 camera issue resolved and one smoke detector by pass by our engineer so it's need to fix in boss office in next visit boss meeting going on so painting. | | |