Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE6284							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9702786668						
Technician Name :	Atique Salmani		Technicia	Technician Mobile: 8080922984			
Ticket Type :	Complain	Date & Time:	01-09-202	01-09-2022 10:21:18			
Vendor Details :							
Company Name/Client Name :	Beam Hospital (Womens Hospital)	Customer's Mobile	97027866	668	Name :	Nazia	
Address:							
Mumbai , , , , Maharashtra							
AMC Details:							
Expiry Date :	30-09-2020 12:00:00 Type : Comprehensive				е		
Product Name:	Fire						
Complain:	2 floor some fire issue hooter is buzzing continuously						
Technician Comment :	we checked fire panell and test 15 to 20 mnts all zones healthy there is some wooden work so it was hootring so need to ppm of fire by blower all sensors need to clean day n time confirm will be Nazia mam.						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	we checked fire panell and test 15 to 20 mnts all zones healthy there is some wooden work so it was hootring so need to ppm of fire by blower all sensors need to clean day n time confirm will be Nazia mam.						
Status History :	Date Time	Technician Name	Status	Remark		Sign	
	01-09-2022 02:01:18	Atique Salmani	Completed	15 to 20 mnts there is some work so it wa need to ppm	of fire by blower eed to clean day n	TREENT	
	01-09-2022 10:21:36	Atique Salmani	New			-	
	01-09-2022 10:21:19	Atique Salmani	New			-	

Previous Complain History :	Date Time	Technician Name	Remark	
	27-06-2022 02:52:19	Siddhesh Chavan	software updated and dives add to software and user download done	
	09-06-2022 12:14:15	Atique Salmani	installation of biomatric device done and make 3 admin Sangeeta mam nazia mam and vallabh 3107 3107 in lan attendence need tonlay cable approx 25to 30 and add employees 8/9.	