Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details: VE7148							
Priority :	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9702786668						
Technician Name :	Atique Salmani		Тє	echnician Mobile :	8080922984		
Ticket Type:	Complain	Date & Time	e : 2:	1-12-2022 10:29:23			
Vendor Details :		-					
Company Name/Client Name :	Beam Hospital (Womens Hospital)	Customer's N	Mobile : 9'	702786668	Name :	Nazia	
Address:							
Mumbai , , , , Maharashtra							
AMC Details:							
Expiry Date :	30-09-2020 12:00:00			pe:	Comprehensive	е	
Product Name:	CCTV						
Complain:	Survey Need to replace 5 cameras There is a dvr on 3rd floor Need to chk dvr is of 4 ch or 8 ch They is 1 camera outside dr rushindra s cabin and 4 cameras on 3rd floor which are to be replaced Also the viewing is to be given to dr rushindra at his place						
Technician Comment :	8 channel dvr 01 SMPS 08 channel.01 Hdd 01 05 / cameras dome And for viewing is same as it is according to Gajala mam Also need to plug point dvr end 4 socket by electrician.its working now vga monitor If on hdmi wants to see then hdmi cable need to lay 10 meters and also monitor need to changed .one camera cabling need to do 7)8 meter $4+1$ cable .						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	8 channel dvr 01 SMPS 08 channel.01 Hdd 01 05 / cameras dome And for viewing is same as it is according to Gajala mam Also need to plug point dvr end 4 socket by electrician.its working now vga monitor If on hdmi wants to see then hdmi cable need to lay 10 meters and also monitor need to changed .one camera cabling need to do 7)8 meter 4+1 cable .						
Status History :	Date Time	Technician Name	Status	Rema	nrk	Sign	
	21-12-2022 10:44:06	Atique Salmani	Completed	8 channel dvr 01 SMP Hdd 01 05 / cameras c viewing is same as it is Gajala mam Also need end 4 socket by electronow vga monitor If on then hdmi cable need and also monitor need camera cabling need t 4+1 cable.	dome And for s according to to plug point dvr ician.its working hdmi wants to see to lay 10 meters to changed .one	X Str	
	21-12-2022 10:29:29	Atique Salmani	New			-	

Previous Complain History:	Date Time	Technician Name	Remark	
	18-11-2022 11:20:27	PravinJagade	Attendance report not proper due to wrong shift setting for employees need to assign proper shift to all employees to get proper report according to shift time and also explained how to do shift setttings.	
	06-11-2022 10:00:00	Atique Salmani	ppm done check fire alarm pannel and cleaned smoke detector and cameras panel working on healthy condition also check by mcp fire and attendence report working ok access make report of all things .and one main gate camera angel settings done.	