




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE5640																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9967522687																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	New Installation	Date & Time :	04-06-2022 10:15:04																						
Vendor Details :																									
Company Name/Client Name :	Damji Shamji - Tivon Park G&H Wing	Customer's Mobile :	9967522687	Name :	Nilesh Mane Sir																				
Address :																									
Mumbai , , , 400086 , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	intercom-VDP																								
Complain :	flat g-04/ h-303 intercom issue h304 new vdp install , new 5 no intercom install																								
Technician Comment :	H wing 303 or 304 new video door phone install and ok working done h wing 303 intercom issue resolved new instrument install f wing 203or 301 only instrument install line off bcz cables missing flat to junction G wing 401/501 /04 new instrument install and ok working done H wing 403 new instrument install and ok working done																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	H wing 303 or 304 new video door phone install and ok working done h wing 303 intercom issue resolved new instrument install f wing 203or 301 only instrument install line off bcz cables missing flat to junction G wing 401/501 /04 new instrument install and ok working done H wing 403 new instrument install and ok working done																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>04-06-2022 04:06:50</td><td>Ravi Rajbhar</td><td>Completed</td><td>H wing 303 or 304 new video door phone install and ok working done h wing 303 intercom issue resolved new instrument install f wing 203or 301 only instrument install line off bcz cables missing flat to junction G wing 401/501 /04 new instrument install and ok working done H wing 403 new instrument install and ok working done</td><td></td></tr><tr><td>04-06-2022 10:15:27</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>04-06-2022 10:15:04</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	04-06-2022 04:06:50	Ravi Rajbhar	Completed	H wing 303 or 304 new video door phone install and ok working done h wing 303 intercom issue resolved new instrument install f wing 203or 301 only instrument install line off bcz cables missing flat to junction G wing 401/501 /04 new instrument install and ok working done H wing 403 new instrument install and ok working done		04-06-2022 10:15:27	Ravi Rajbhar	New		-	04-06-2022 10:15:04	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
04-06-2022 04:06:50	Ravi Rajbhar	Completed	H wing 303 or 304 new video door phone install and ok working done h wing 303 intercom issue resolved new instrument install f wing 203or 301 only instrument install line off bcz cables missing flat to junction G wing 401/501 /04 new instrument install and ok working done H wing 403 new instrument install and ok working done																						
04-06-2022 10:15:27	Ravi Rajbhar	New		-																					
04-06-2022 10:15:04	Ravi Rajbhar	New		-																					

Previous Complain History :			
	Date Time	Technician Name	Remark
	04-05-2022 06:42:49	YogeshDesai	G wing 302 intercom issue solved line working ok and phone too
	20-04-2022 11:43:34	Atique Salmani	it's g 804 not. h 804 check and resolve issue only phone was hang not punch in crone so chack cable and punch working ok.