




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE5869</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9967522687																								
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	05-07-2022 10:15:47																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Damji Shamji - Tivon Park F Wing	<b>Customer's Mobile :</b>	9967522687	<b>Name :</b>	Nilesh Mane Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	Intercom																								
<b>Complain :</b>	reception intercom issue																								
<b>Technician Comment :</b>	system was hang so it was ringing continue sonrestart and check working ok. boath wing on under observation.																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	system was hang so it was ringing continue sonrestart and check working ok. boath wing on under observation.																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-07-2022 04:29:41</td><td>Atique Salmani</td><td>Completed</td><td>system was hang so it was ringing continue sonrestart and check working ok. boath wing on under observation.</td><td></td></tr><tr><td>05-07-2022 10:17:31</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>05-07-2022 10:15:47</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-07-2022 04:29:41	Atique Salmani	Completed	system was hang so it was ringing continue sonrestart and check working ok. boath wing on under observation.		05-07-2022 10:17:31	Atique Salmani	New		-	05-07-2022 10:15:47	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
05-07-2022 04:29:41	Atique Salmani	Completed	system was hang so it was ringing continue sonrestart and check working ok. boath wing on under observation.																						
05-07-2022 10:17:31	Atique Salmani	New		-																					
05-07-2022 10:15:47	Atique Salmani	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>20-04-2022 11:41:19</td><td>Atique Salmani</td><td>703 803 f wing checks and also not punch in system and also rest date and time f wing g wing pannel was off now taping on swich .</td></tr><tr><td>16-02-2022 10:35:39</td><td>Siddhesh Chavan</td><td>f wing mine lobby intercom issue resolved and system off and issue resolved</td></tr></tbody></table>					Date Time	Technician Name	Remark	20-04-2022 11:41:19	Atique Salmani	703 803 f wing checks and also not punch in system and also rest date and time f wing g wing pannel was off now taping on swich .	16-02-2022 10:35:39	Siddhesh Chavan	f wing mine lobby intercom issue resolved and system off and issue resolved											
Date Time	Technician Name	Remark																							
20-04-2022 11:41:19	Atique Salmani	703 803 f wing checks and also not punch in system and also rest date and time f wing g wing pannel was off now taping on swich .																							
16-02-2022 10:35:39	Siddhesh Chavan	f wing mine lobby intercom issue resolved and system off and issue resolved																							