

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6039																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9967522687																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Complain	Date & Time :	26-07-2022 11:00:12																						
Vendor Details :																									
Company Name/Client Name :	Damji Shamji - Tivon Park G&H Wing	Customer's Mobile :	9967522687	Name :	Nilesh Mane Sir																				
Address :																									
Mumbai , , , 400086 , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Intercom																								
Complain :	H-804, H-604, H-404, H-203 new intercom installation																								
Technician Comment :	H wing instrument install 804 cable missing 604 ok 404 ok 203 ok																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	H wing instrument install 804 cable missing 604 ok 404 ok 203 ok																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-07-2022 05:24:35</td><td>Ravi Rajbhar</td><td>Completed</td><td>H wing instrument install 804 cable missing 604 ok 404 ok 203 ok</td><td></td></tr><tr><td>26-07-2022 11:00:31</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>26-07-2022 11:00:12</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-07-2022 05:24:35	Ravi Rajbhar	Completed	H wing instrument install 804 cable missing 604 ok 404 ok 203 ok		26-07-2022 11:00:31	Ravi Rajbhar	New		-	26-07-2022 11:00:12	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
26-07-2022 05:24:35	Ravi Rajbhar	Completed	H wing instrument install 804 cable missing 604 ok 404 ok 203 ok																						
26-07-2022 11:00:31	Ravi Rajbhar	New		-																					
26-07-2022 11:00:12	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>06-07-2022 04:57:06</td><td>Shiva Meena</td><td>h wing 602 intrcom ok and intrcom ristart done</td></tr><tr><td>05-07-2022 10:17:11</td><td>Atique Salmani</td><td>g wing reception intrcom issue resolved check call by 303 working ok.</td></tr></tbody></table>					Date Time	Technician Name	Remark	06-07-2022 04:57:06	Shiva Meena	h wing 602 intrcom ok and intrcom ristart done	05-07-2022 10:17:11	Atique Salmani	g wing reception intrcom issue resolved check call by 303 working ok.											
Date Time	Technician Name	Remark																							
06-07-2022 04:57:06	Shiva Meena	h wing 602 intrcom ok and intrcom ristart done																							
05-07-2022 10:17:11	Atique Salmani	g wing reception intrcom issue resolved check call by 303 working ok.																							