




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8073</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9967522687																			
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	08-04-2023 04:40:47																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Damji Shamji - Tivon Park G&H Wing	Customer's Mobile :	9967522687	Name :	Nilesh Mane Sir															
<b>Address :</b>																				
Mumbai , , , 400086 , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	4 nos 4x4 box need to install and Old gate + Container cameras not able to view online In mobile																			
<b>Technician Comment :</b>	4*4 box =2 h wing change main entrance and online issue resolved user ID- tivonpark_123 password - admin@123 verification code - Admin123 and contenor side one camera blur issue resolved need to change bnc pin																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	4*4 box =2 h wing change main entrance and online issue resolved user ID- tivonpark_123 password - admin@123 verification code - Admin123 and contenor side one camera blur issue resolved need to change bnc pin																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-04-2023 05:55:39</td><td>Ravi Rajbhar</td><td>Completed</td><td>4*4 box =2 h wing change main entrance and online issue resolved user ID- tivonpark_123 password - admin@123 verification code - Admin123 and contenor side one camera blur issue resolved need to change bnc pin</td><td></td></tr><tr><td>08-04-2023 04:41:07</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-04-2023 05:55:39	Ravi Rajbhar	Completed	4*4 box =2 h wing change main entrance and online issue resolved user ID- tivonpark_123 password - admin@123 verification code - Admin123 and contenor side one camera blur issue resolved need to change bnc pin		08-04-2023 04:41:07	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
08-04-2023 05:55:39	Ravi Rajbhar	Completed	4*4 box =2 h wing change main entrance and online issue resolved user ID- tivonpark_123 password - admin@123 verification code - Admin123 and contenor side one camera blur issue resolved need to change bnc pin																	
08-04-2023 04:41:07	Ravi Rajbhar	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>03-04-2023 03:14:53</td><td>SantoshPathak</td><td>I ball guard 12 Volt power supply faulty 12volt power supply is damaged by overloading a new power supply will be required. 04.04.2023 - Kalpesh visited - 12V 8 ch power supply installed done 8 camera working properly sales office DVR online done</td></tr><tr><td>03-04-2023 11:03:19</td><td>SantoshPathak</td><td>G wing security lobby extension ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	03-04-2023 03:14:53	SantoshPathak	I ball guard 12 Volt power supply faulty 12volt power supply is damaged by overloading a new power supply will be required. 04.04.2023 - Kalpesh visited - 12V 8 ch power supply installed done 8 camera working properly sales office DVR online done	03-04-2023 11:03:19	SantoshPathak	G wing security lobby extension ok						
Date Time	Technician Name	Remark																		
03-04-2023 03:14:53	SantoshPathak	I ball guard 12 Volt power supply faulty 12volt power supply is damaged by overloading a new power supply will be required. 04.04.2023 - Kalpesh visited - 12V 8 ch power supply installed done 8 camera working properly sales office DVR online done																		
03-04-2023 11:03:19	SantoshPathak	G wing security lobby extension ok																		