

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3056					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9967522687				
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764	
Ticket Type :	New Installation	Date & Time :	07-05-2021 09:52:39		
Vendor Details :					
Company Name/Client Name :	Tivon Park F Wing	Customer's Mobile :	9967522687	Name :	Nilesh Sir
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	VDP				
Complain :	h wing - 802 , 602 g wing - 801 , 604 , 402 , 301 f wing - 802 , 601 , 501 , 502 , 503				
Technician Comment :	Tivon Park 1.H.602 done 2.F. 802 done 3.F.601 lock painding client side out door Wire not drop 4.F.501 painding cable not on positon 5.F.503 done 6.F. 502 done 7.F. 201 done 8.F.602 done 9.G.801 done 10.G.604 done 11.G.402 done 12.G.301 painding renewal going on.. Total 9 vdp installed and working ok.				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	Tivon Park 1.H.602 done 2.F. 802 done 3.F.601 lock painding client side out door Wire not drop 4.F.501 painding cable not on positon 5.F.503 done 6.F. 502 done 7.F. 201 done 8.F.602 done 9.G.801 done 10.G.604 done 11.G.402 done 12.G.301 painding renewal going on.. Total 9 vdp installed and working ok.				

Status History :	Date Time	Technician Name	Status	Remark	Sign
	08-05-2021 05:08:33	Neeraj Chauhan	Completed	Tivon Park 1.H.602 done 2.F. 802 done 3.F.601 lock painding client side out door Wire not drop 4.F.501 painding cable not on positon 5.F.503 done 6.F. 502 done 7.F. 201 done 8.F.602 done : 9.G.801 done 10.G.604 done 11.G.402 done 12.G.301 painding renewal going on.. Total 9 vdp installed and working ok.	
	07-05-2021 07:14:54	Neeraj Chauhan	New		-
	07-05-2021 04:24:50	Neeraj Chauhan	Work Pending	work painding bucoz diomond pana didn't get so painding and local Configration done on PC office Dvr USB boath issue and also HDMI port issue so its also painding .	
	07-05-2021 09:52:50	Neeraj Chauhan	New		-
	07-05-2021 09:52:39	Neeraj Chauhan	New		-
Previous Complain History :	Date Time	Technician Name	Remark		
	26-07-2023 10:43:34	InzmamUl Haq			
	05-07-2023 12:52:13	PravinJagade	CCTV. Intercom,vdp ppm done all camera working. 803/804 phone issue resolve working done.		