

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3466																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9967522687																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	New Installation	Date & Time :	20-07-2021 10:10:49																						
Vendor Details :																									
Company Name/Client Name :	Tivon Park F Wing	Customer's Mobile :	9967522687	Name :	Nilesh Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	VDP																								
Complain :	In F701, F702, F703, F704, F801 need to do vdp & intercom installation																								
Technician Comment :	new vdp install F wing 701 ,702, 801 ,504 with intercom same flat G wing 603 with intercom camplenit resolved F wing 601 line ok instrument issue 802 G wing 503/003 graund floor/803 cable issue H wing 801 new intercom phone install/ 002 ground floor																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	new vdp install F wing 701 ,702, 801 ,504 with intercom same flat G wing 603 with intercom camplenit resolved F wing 601 line ok instrument issue 802 G wing 503/003 graund floor/803 cable issue H wing 801 new intercom phone install/ 002 ground floor																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>20-07-2021 07:00:41</td><td>Ravi Rajbhar</td><td>Completed</td><td>new vdp install F wing 701 ,702, 801 ,504 with intercom same flat G wing 603 with intercom camplenit resolved F wing 601 line ok instrument issue 802 G wing 503/003 graund floor/803 cable issue H wing 801 new intercom phone install/ 002 ground floor</td><td></td></tr><tr><td>20-07-2021 10:11:12</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>20-07-2021 10:10:49</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	20-07-2021 07:00:41	Ravi Rajbhar	Completed	new vdp install F wing 701 ,702, 801 ,504 with intercom same flat G wing 603 with intercom camplenit resolved F wing 601 line ok instrument issue 802 G wing 503/003 graund floor/803 cable issue H wing 801 new intercom phone install/ 002 ground floor		20-07-2021 10:11:12	Ravi Rajbhar	New		-	20-07-2021 10:10:49	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
20-07-2021 07:00:41	Ravi Rajbhar	Completed	new vdp install F wing 701 ,702, 801 ,504 with intercom same flat G wing 603 with intercom camplenit resolved F wing 601 line ok instrument issue 802 G wing 503/003 graund floor/803 cable issue H wing 801 new intercom phone install/ 002 ground floor																						
20-07-2021 10:11:12	Ravi Rajbhar	New		-																					
20-07-2021 10:10:49	Ravi Rajbhar	New		-																					

Previous Complain History :	Date Time	Technician Name	Remark
	26-07-2023 10:43:34	InzmamUl Haq	
	05-07-2023 12:52:13	PravinJagade	CCTV. Intercom,vdp ppm done all camera working. 803/804 phone issue resolve working done.