

# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8340</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9967522687																								
<b>Technician Name :</b>	Santosh Pathak		<b>Technician Mobile :</b>	8080922980																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	13-05-2023 10:21:03																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Tivon Park G&H Wing	<b>Customer's Mobile :</b>	9967522687	<b>Name :</b>	Nilesh Sir																				
<b>Address :</b>																									
Mumbai , , , 400086 , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	need to show recording h wing and sales office camera recording 5th may night 10 to 12th may																								
<b>Technician Comment :</b>																									
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	recording shown and given in pendrive																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>13-05-2023 06:33:37</td><td>SantoshPathak</td><td>Completed</td><td></td><td>-</td></tr><tr><td>13-05-2023 06:30:35</td><td>SantoshPathak</td><td>Completed</td><td></td><td>-</td></tr><tr><td>13-05-2023 10:21:13</td><td>SantoshPathak</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	13-05-2023 06:33:37	SantoshPathak	Completed		-	13-05-2023 06:30:35	SantoshPathak	Completed		-	13-05-2023 10:21:13	SantoshPathak	New		-
Date Time	Technician Name	Status	Remark	Sign																					
13-05-2023 06:33:37	SantoshPathak	Completed		-																					
13-05-2023 06:30:35	SantoshPathak	Completed		-																					
13-05-2023 10:21:13	SantoshPathak	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>03-05-2023 02:27:15</td><td>Ishwar Meena</td><td>(1) main gate camera recording issue resolved. Record working ok. (2) H wing one camera angle set. (3) H wing lift camera off issue resolved and working ok.</td></tr><tr><td>28-04-2023 03:19:29</td><td>Atique Salmani</td><td>16 ch. Hikvision Dvr 2 SMPS 3 bullet 1 ptz Container to sale's office distance 80. /to 85 meter every camera all cable rj6 aarmor For ptz also 2 core aarmor cable All camera need to on joint according to Rohit sir</td></tr></tbody></table>					Date Time	Technician Name	Remark	03-05-2023 02:27:15	Ishwar Meena	(1) main gate camera recording issue resolved. Record working ok. (2) H wing one camera angle set. (3) H wing lift camera off issue resolved and working ok.	28-04-2023 03:19:29	Atique Salmani	16 ch. Hikvision Dvr 2 SMPS 3 bullet 1 ptz Container to sale's office distance 80. /to 85 meter every camera all cable rj6 aarmor For ptz also 2 core aarmor cable All camera need to on joint according to Rohit sir											
Date Time	Technician Name	Remark																							
03-05-2023 02:27:15	Ishwar Meena	(1) main gate camera recording issue resolved. Record working ok. (2) H wing one camera angle set. (3) H wing lift camera off issue resolved and working ok.																							
28-04-2023 03:19:29	Atique Salmani	16 ch. Hikvision Dvr 2 SMPS 3 bullet 1 ptz Container to sale's office distance 80. /to 85 meter every camera all cable rj6 aarmor For ptz also 2 core aarmor cable All camera need to on joint according to Rohit sir																							