







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13650																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	8097724200																													
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																										
Ticket Type :	Complain	Date & Time :	26-12-2024 03:00:18																											
Vendor Details :																														
Company Name/Client Name :	Fortune Acres Malik Bhai	Customer's Mobile :	8097724200	Name :	Noor Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	PTZ Camera not working																													
Technician Comment :	Power connector changed and data camera female connector also some rushted so if again off then camera need to remooved and collect for changed female connector																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	Power connector changed and data camera female connector also some rushted so if again off then camera need to remooved and collect for changed female connector																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-12-2024 03:19:18</td><td>Atique Salmani</td><td>Completed</td><td>Power connector changed and data camera female connector also some rushted so if again off then camera need to remooved and collect for changed female connector</td><td></td></tr><tr><td>30-12-2024 10:59:04</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>27-12-2024 02:52:01</td><td>Atique Salmani</td><td>Work Pending</td><td>Ptz Camera power concter issue need Change concter 2pin. Call yet to be closed</td><td></td></tr><tr><td>27-12-2024 01:20:50</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	30-12-2024 03:19:18	Atique Salmani	Completed	Power connector changed and data camera female connector also some rushted so if again off then camera need to remooved and collect for changed female connector		30-12-2024 10:59:04	Atique Salmani	New		-	27-12-2024 02:52:01	Atique Salmani	Work Pending	Ptz Camera power concter issue need Change concter 2pin. Call yet to be closed		27-12-2024 01:20:50	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
30-12-2024 03:19:18	Atique Salmani	Completed	Power connector changed and data camera female connector also some rushted so if again off then camera need to remooved and collect for changed female connector																											
30-12-2024 10:59:04	Atique Salmani	New		-																										
27-12-2024 02:52:01	Atique Salmani	Work Pending	Ptz Camera power concter issue need Change concter 2pin. Call yet to be closed																											
27-12-2024 01:20:50	Atique Salmani	New		-																										

Previous Complain History :			
	Date Time	Technician Name	Remark
	23-12-2024 10:25:42	Shiva Meena	2 ip camera ricnecsan done work completed
	21-12-2024 11:21:19	Shiva Meena	Cebling cet6 old 112 miter and aarmad cebling cet6 70 Miter 3 nuw camera install and 2 old camera with 25 Miter cebling old done work completed