

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | **W :** www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4690																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	8097647294																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Complain	Date & Time :	01-02-2022 03:35:01																						
Vendor Details :																									
Company Name/Client Name :	Swapnalok CHS	Customer's Mobile :	8097647294	Name :	Pande																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	31-05-2021 12:00:00		Type :	Comprehensive																					
Product Name :	Intercom																								
Complain :	security intercom issue and b wing 503 intercom issue																								
Technician Comment :	security office port issue and new port used 115 with reprogramming 97 b wing 502 intercom issue resolved 503 cable issue flat to ground floor system a wing 402 intercom issue resolved																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	security office port issue and new port used 115 with reprogramming 97 b wing 502 intercom issue resolved 503 cable issue flat to ground floor system a wing 402 intercom issue resolved																								
Status History :	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Status</th> <th>Remark</th> <th>Sign</th> </tr> </thead> <tbody> <tr> <td>01-02-2022 06:45:18</td> <td>Ravi Rajbhar</td> <td>Completed</td> <td>security office port issue and new port used 115 with reprogramming 97 b wing 502 intercom issue resolved 503 cable issue flat to ground floor system a wing 402 intercom issue resolved</td> <td></td> </tr> <tr> <td>01-02-2022 03:35:14</td> <td>Ravi Rajbhar</td> <td>New</td> <td></td> <td>-</td> </tr> <tr> <td>01-02-2022 03:35:01</td> <td>Ravi Rajbhar</td> <td>New</td> <td></td> <td>-</td> </tr> </tbody> </table>					Date Time	Technician Name	Status	Remark	Sign	01-02-2022 06:45:18	Ravi Rajbhar	Completed	security office port issue and new port used 115 with reprogramming 97 b wing 502 intercom issue resolved 503 cable issue flat to ground floor system a wing 402 intercom issue resolved		01-02-2022 03:35:14	Ravi Rajbhar	New		-	01-02-2022 03:35:01	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
01-02-2022 06:45:18	Ravi Rajbhar	Completed	security office port issue and new port used 115 with reprogramming 97 b wing 502 intercom issue resolved 503 cable issue flat to ground floor system a wing 402 intercom issue resolved																						
01-02-2022 03:35:14	Ravi Rajbhar	New		-																					
01-02-2022 03:35:01	Ravi Rajbhar	New		-																					
Previous Complain History :	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Remark</th> </tr> </thead> <tbody> <tr> <td>05-03-2022 01:51:03</td> <td>Prashant Nikalje</td> <td>b wing 202 out side camera add pending a wing 302 door lock 08.03.2022 - A301/A302 - Volume setting A-502 - Access finger add B-603 - Access finger add B-303 - Mobile app configure B-103 - Mobile app configure B-201 - VDP screen camera add B-202 - VDP screen camera add</td> </tr> <tr> <td>05-03-2022 01:42:58</td> <td>Ravi Rajbhar</td> <td>security cabin intercom issue resolved rh 12 reconnection and ok working done</td> </tr> </tbody> </table>					Date Time	Technician Name	Remark	05-03-2022 01:51:03	Prashant Nikalje	b wing 202 out side camera add pending a wing 302 door lock 08.03.2022 - A301/A302 - Volume setting A-502 - Access finger add B-603 - Access finger add B-303 - Mobile app configure B-103 - Mobile app configure B-201 - VDP screen camera add B-202 - VDP screen camera add	05-03-2022 01:42:58	Ravi Rajbhar	security cabin intercom issue resolved rh 12 reconnection and ok working done											
Date Time	Technician Name	Remark																							
05-03-2022 01:51:03	Prashant Nikalje	b wing 202 out side camera add pending a wing 302 door lock 08.03.2022 - A301/A302 - Volume setting A-502 - Access finger add B-603 - Access finger add B-303 - Mobile app configure B-103 - Mobile app configure B-201 - VDP screen camera add B-202 - VDP screen camera add																							
05-03-2022 01:42:58	Ravi Rajbhar	security cabin intercom issue resolved rh 12 reconnection and ok working done																							