

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7803																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	8097647294																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	08-03-2023 11:35:45																	
Vendor Details :																				
Company Name/Client Name :	Swapnalok CHS	Customer's Mobile :	8097647294	Name :	Pande															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	31-05-2021 12:00:00		Type :	Comprehensive																
Product Name :	VDP																			
Complain :	3 No vdp not working and also mobile online View issue																			
Technician Comment :	A wing 701 video door phone no video issue resolved and ok working done reconfiration done with online done and interco check																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	A wing 701 video door phone no video issue resolved and ok working done reconfiration done with online done and interco check																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-03-2023 03:05:41</td><td>Ravi Rajbhar</td><td>Completed</td><td>A wing 701 video door phone no video issue resolved and ok working done reconfiration done with online done and interco check</td><td>Rkg</td></tr><tr><td>08-03-2023 11:35:53</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-03-2023 03:05:41	Ravi Rajbhar	Completed	A wing 701 video door phone no video issue resolved and ok working done reconfiration done with online done and interco check	Rkg	08-03-2023 11:35:53	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
08-03-2023 03:05:41	Ravi Rajbhar	Completed	A wing 701 video door phone no video issue resolved and ok working done reconfiration done with online done and interco check	Rkg																
08-03-2023 11:35:53	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-03-2023 10:50:40</td><td>Prashant Nikalje</td><td></td></tr><tr><td>06-03-2023 10:04:29</td><td>Ravi Rajbhar</td><td>A wing monitor off bec in plug point power not coming so painding also check a wing 401 intercom working ok. And lift monitor blinking need 60 metr hdmi cable changed and also rj 45 recrimp but same issue so need to check with hdmi extender 60 metr .</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-03-2023 10:50:40	Prashant Nikalje		06-03-2023 10:04:29	Ravi Rajbhar	A wing monitor off bec in plug point power not coming so painding also check a wing 401 intercom working ok. And lift monitor blinking need 60 metr hdmi cable changed and also rj 45 recrimp but same issue so need to check with hdmi extender 60 metr .						
Date Time	Technician Name	Remark																		
14-03-2023 10:50:40	Prashant Nikalje																			
06-03-2023 10:04:29	Ravi Rajbhar	A wing monitor off bec in plug point power not coming so painding also check a wing 401 intercom working ok. And lift monitor blinking need 60 metr hdmi cable changed and also rj 45 recrimp but same issue so need to check with hdmi extender 60 metr .																		