Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE8398 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9820497776 **No. : Technician Name** Atique Salmani **Technician Mobile** 8080922984 Complain 22-05-2023 10:41:12 **Ticket Type :** Date & Time : Vendor Details : Piyush Sayani Customer's Mobile 9820497776 Poonam Company Name : Name/Client Name Madam Ref Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** VDP VDP issue - Memory not saving and some timing issue - 750/- visiting charges need to collect **Complain**: Screen Installed after firmware update now working ok. with recording .also received payment Technician **Comment** : 600./ Complain Desktop - Apurva Vajaria **Operator** : **Remark** : Screen Installed after firmware update now working ok. with recording .also received payment 600./ **Status History : Date Time Technician Name** Status Remark Sign 26-05-2023 10:20:43 Atique Salmani Completed Screen Installed after 2ps firmware update now working ok. with recording .also received payment 600./ 26-05-2023 10:09:25 Atique Salmani New 26-05-2023 10:08:59 Atique Salmani New 22-05-2023 12:24:49 Atique Salmani Work Pending Screen didn't read memory card and not being factory default so collect only screen for check and test 22-05-2023 10:41:34 Atique Salmani New Previous **Date Time Technician Name** Remark **Complain History** 26-05-2023 06:47:03 Atique Salmani Dvr settings changed motion senstivity before was high now keep it on normal now working ok and keep it under observation for 2 days .