




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8784</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9004700906																			
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	10-07-2023 10:28:43																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Value Beverage	Customer's Mobile :	9004700906	Name :	Poonam Madam															
<b>Address :</b>																				
Mumbai , , , 400710 , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
<b>Product Name :</b>	Access																			
<b>Complain :</b>	access door lock issue																			
<b>Technician Comment :</b>	Basement lock was moving so remooved totally and reinstalled proper And also reconnection from pannel working ok and on under observation and 1 St floor lock faulty need to changed em lock And 3 floor toilet side lock alliingment done and magnet fixed proper . Also checked production room door lock .																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	Basement lock was moving so remooved totally and reinstalled proper And also reconnection from pannel working ok and on under observation and 1 St floor lock faulty need to changed em lock And 3 floor toilet side lock alliingment done and magnet fixed proper . Also checked production room door lock .																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-07-2023 01:30:06</td><td>Atique Salmani</td><td>Completed</td><td>Basement lock was moving so remooved totally and reinstalled proper And also reconnection from pannel working ok and on under observation and 1 St floor lock faulty need to changed em lock And 3 floor toilet side lock alliingment done and magnet fixed proper . Also checked production room door lock .</td><td></td></tr><tr><td>10-07-2023 10:28:50</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-07-2023 01:30:06	Atique Salmani	Completed	Basement lock was moving so remooved totally and reinstalled proper And also reconnection from pannel working ok and on under observation and 1 St floor lock faulty need to changed em lock And 3 floor toilet side lock alliingment done and magnet fixed proper . Also checked production room door lock .		10-07-2023 10:28:50	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
10-07-2023 01:30:06	Atique Salmani	Completed	Basement lock was moving so remooved totally and reinstalled proper And also reconnection from pannel working ok and on under observation and 1 St floor lock faulty need to changed em lock And 3 floor toilet side lock alliingment done and magnet fixed proper . Also checked production room door lock .																	
10-07-2023 10:28:50	Atique Salmani	New		-																

Previous Complain History :			
	Date Time	Technician Name	Remark
	13-06-2023 10:53:23	MayurYadav	Ground floor Access door push button cable one pair not working Pair change door working ok open with push button
	08-06-2023 10:47:32	Siddhesh Chavan	18 card adding done and new power supply install and door lock issue resoved and old supply take to Poonam madam