

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14358																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9967030125																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	24-03-2025 06:39:47																	
Vendor Details :																				
Company Name/Client Name :	Raj Akshay Miraroad	Customer's Mobile :	9967030125	Name :	Pramod Bhai															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	VDP																			
Complain :	vdp issue and compliant need to give training to pramod bhai																			
Technician Comment :	A wing 504 , 303 door lock not available client B wing 1101 issue resolved C wing 2201 , 301 issue resolved																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	A wing 504 , 303 door lock not available client B wing 1101 issue resolved C wing 2201 , 301 issue resolved																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-03-2025 01:21:12</td><td>Ravi Rajbhar</td><td>Completed</td><td>A wing 504 , 303 door lock not available client B wing 1101 issue resolved C wing 2201 , 301 issue resolved</td><td></td></tr><tr><td>24-03-2025 06:40:02</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-03-2025 01:21:12	Ravi Rajbhar	Completed	A wing 504 , 303 door lock not available client B wing 1101 issue resolved C wing 2201 , 301 issue resolved		24-03-2025 06:40:02	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
25-03-2025 01:21:12	Ravi Rajbhar	Completed	A wing 504 , 303 door lock not available client B wing 1101 issue resolved C wing 2201 , 301 issue resolved																	
24-03-2025 06:40:02	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>16-01-2025 01:03:23</td><td>Rahul Mhapralkar</td><td></td></tr><tr><td>04-01-2025 12:12:58</td><td>Ravi Rajbhar</td><td>Ravi and Manoj visited on 07.01.2024 C wing new vdp install 301 , 201 Complaint 706 , 1601 1802 , 202 , 2204 vdp issue resolved and ok working done And 301 need to change cable flat to junction A wing wing new install vdp - 301 ,201 , 404 But lobby video not viewing flat cable check then need to change cable</td></tr></tbody></table>					Date Time	Technician Name	Remark	16-01-2025 01:03:23	Rahul Mhapralkar		04-01-2025 12:12:58	Ravi Rajbhar	Ravi and Manoj visited on 07.01.2024 C wing new vdp install 301 , 201 Complaint 706 , 1601 1802 , 202 , 2204 vdp issue resolved and ok working done And 301 need to change cable flat to junction A wing wing new install vdp - 301 ,201 , 404 But lobby video not viewing flat cable check then need to change cable						
Date Time	Technician Name	Remark																		
16-01-2025 01:03:23	Rahul Mhapralkar																			
04-01-2025 12:12:58	Ravi Rajbhar	Ravi and Manoj visited on 07.01.2024 C wing new vdp install 301 , 201 Complaint 706 , 1601 1802 , 202 , 2204 vdp issue resolved and ok working done And 301 need to change cable flat to junction A wing wing new install vdp - 301 ,201 , 404 But lobby video not viewing flat cable check then need to change cable																		