




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1503																									
Priority :	High																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9987588911																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	26-06-2020 04:28:08																						
Vendor Details :																									
Company Name/Client Name :	Chandrakant Residency	Customer's Mobile :	9987588911	Name :	Prashant Sir																				
Address :																									
Thane , Maxus Mall Road, Padmavati Nagar, Bhayandar West, Mira Bhayandar, Maharashtra, India , , , Maharashtra																									
AMC Details :																									
Expiry Date :	31-01-2021 12:00:00		Type :	Non-Comprehensive																					
Product Name :	CCTV																								
Complain :	2-3 pipe installation garden area as pipe is been damaged																								
Technician Comment :	garden back side 2pipe 25 mm use and one camera housing and stand changed and also 4*4box changed.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	garden back side 2pipe 25 mm use and one camera housing and stand changed and also 4*4box changed.																								
Status History :	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Status</th> <th>Remark</th> <th>Sign</th> </tr> </thead> <tbody> <tr> <td>01-07-2020 07:43:37</td> <td>Atique Salmani</td> <td>Completed</td> <td>garden back side 2pipe 25 mm use and one camera housing and stand changed and also 4*4box changed.</td> <td></td> </tr> <tr> <td>01-07-2020 07:05:03</td> <td>Atique Salmani</td> <td>New</td> <td></td> <td>-</td> </tr> <tr> <td>26-06-2020 04:28:09</td> <td>Atique Salmani</td> <td>New</td> <td></td> <td>-</td> </tr> </tbody> </table>					Date Time	Technician Name	Status	Remark	Sign	01-07-2020 07:43:37	Atique Salmani	Completed	garden back side 2pipe 25 mm use and one camera housing and stand changed and also 4*4box changed.		01-07-2020 07:05:03	Atique Salmani	New		-	26-06-2020 04:28:09	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
01-07-2020 07:43:37	Atique Salmani	Completed	garden back side 2pipe 25 mm use and one camera housing and stand changed and also 4*4box changed.																						
01-07-2020 07:05:03	Atique Salmani	New		-																					
26-06-2020 04:28:09	Atique Salmani	New		-																					
Previous Complain History :	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Remark</th> </tr> </thead> <tbody> <tr> <td>07-09-2020 01:09:09</td> <td>Atique Salmani</td> <td>cctv issue main gate camera not working reset camera and working ok. and intetcom 3 line issue repunch from crone flate nmbr B Wing 602 bwing 103 and 403 cable trace and line ok instrument keypad issue need to changed.</td> </tr> <tr> <td>12-08-2020 11:36:20</td> <td>AnilYadav</td> <td>Anil Visited an changed ballon and now working ok</td> </tr> </tbody> </table>					Date Time	Technician Name	Remark	07-09-2020 01:09:09	Atique Salmani	cctv issue main gate camera not working reset camera and working ok. and intetcom 3 line issue repunch from crone flate nmbr B Wing 602 bwing 103 and 403 cable trace and line ok instrument keypad issue need to changed.	12-08-2020 11:36:20	AnilYadav	Anil Visited an changed ballon and now working ok											
Date Time	Technician Name	Remark																							
07-09-2020 01:09:09	Atique Salmani	cctv issue main gate camera not working reset camera and working ok. and intetcom 3 line issue repunch from crone flate nmbr B Wing 602 bwing 103 and 403 cable trace and line ok instrument keypad issue need to changed.																							
12-08-2020 11:36:20	AnilYadav	Anil Visited an changed ballon and now working ok																							