




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE1941</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9987588911																								
<b>Technician Name :</b>	Anil Yadav		<b>Technician Mobile :</b>	8080922983																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	01-10-2020 06:22:26																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Chandrakant Residency	Customer's Mobile :	9987588911	Name :	Prashant Sir																				
<b>Address :</b>																									
Thane , Maxus Mall Road, Padmavati Nagar, Bhayandar West, Mira Bhayandar, Maharashtra, India , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	31-01-2021 12:00:00		Type :	Non-Comprehensive																					
<b>Product Name :</b>	Intercom																								
<b>Complain :</b>	b wing 203 204 402 202																								
<b>Technician Comment :</b>	B/202 all ready inform cable issue. B/203 Karon side cable connection was dead. I do pepper connection after working condition. B/204 phone is dead need to new phone. B/402 New phone install working fine. phone is client. A/604 phone is dead need to change.																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	B/202 all ready inform cable issue. B/203 Karon side cable connection was dead. I do pepper connection after working condition. B/204 phone is dead need to new phone. B/402 New phone install working fine. phone is client. A/604 phone is dead need to change.																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-10-2020 06:52:25</td><td>AnilYadav</td><td>Completed</td><td>B/202 all ready inform cable issue. B/203 Karon side cable connection was dead. I do pepper connection after working condition. B/204 phone is dead need to new phone. B/402 New phone install working fine. phone is client. A/604 phone is dead need to change.</td><td></td></tr><tr><td>03-10-2020 10:31:09</td><td>AnilYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>01-10-2020 06:22:26</td><td>AnilYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-10-2020 06:52:25	AnilYadav	Completed	B/202 all ready inform cable issue. B/203 Karon side cable connection was dead. I do pepper connection after working condition. B/204 phone is dead need to new phone. B/402 New phone install working fine. phone is client. A/604 phone is dead need to change.		03-10-2020 10:31:09	AnilYadav	New		-	01-10-2020 06:22:26	AnilYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																					
03-10-2020 06:52:25	AnilYadav	Completed	B/202 all ready inform cable issue. B/203 Karon side cable connection was dead. I do pepper connection after working condition. B/204 phone is dead need to new phone. B/402 New phone install working fine. phone is client. A/604 phone is dead need to change.																						
03-10-2020 10:31:09	AnilYadav	New		-																					
01-10-2020 06:22:26	AnilYadav	New		-																					

Previous Complain History :			
	Date Time	Technician Name	Remark
	23-06-2022 10:28:11	Siddhesh Chavan	mine gate intercom issue resolved and 750 rs cash received
	24-05-2022 05:15:38	Javed Bhaldar	there is no junction box there is mtnl box shown the security person