




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE12932																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9821011523																			
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764																
Ticket Type :	Complain	Date & Time :	08-10-2024 03:31:39																	
Vendor Details :																				
Company Name/Client Name :	Veena Sur Co-op Hsg	Customer's Mobile :	9821011523	Name :	Pratik Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	2 cameras angle need to set																			
Technician Comment :	2 camera angle setting done b wing and c wing Main gate camera sifting required																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	2 camera angle setting done b wing and c wing Main gate camera sifting required																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>09-10-2024 11:56:23</td><td>Neeraj Chauhan</td><td>Work Pending</td><td>2 camera angle setting done b wing and c wing Main gate camera sifting required</td><td></td></tr><tr><td>09-10-2024 10:58:48</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	09-10-2024 11:56:23	Neeraj Chauhan	Work Pending	2 camera angle setting done b wing and c wing Main gate camera sifting required		09-10-2024 10:58:48	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																
09-10-2024 11:56:23	Neeraj Chauhan	Work Pending	2 camera angle setting done b wing and c wing Main gate camera sifting required																	
09-10-2024 10:58:48	Neeraj Chauhan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>31-12-2024 10:18:03</td><td>Ravi Rajbhar</td><td>Cctv camera Recoding show to client and backup given to pendrive and one cmaera survey done new cabling 15- 20 meter aprox (old need to check before then new cabling) Poe switch all port full near by</td></tr><tr><td>13-12-2024 01:25:12</td><td>Siddhesh Chavan</td><td>Systeam off issue resoved because systeam Disconnect recontct systeam and working ok in lobby</td></tr></tbody></table>					Date Time	Technician Name	Remark	31-12-2024 10:18:03	Ravi Rajbhar	Cctv camera Recoding show to client and backup given to pendrive and one cmaera survey done new cabling 15- 20 meter aprox (old need to check before then new cabling) Poe switch all port full near by	13-12-2024 01:25:12	Siddhesh Chavan	Systeam off issue resoved because systeam Disconnect recontct systeam and working ok in lobby						
Date Time	Technician Name	Remark																		
31-12-2024 10:18:03	Ravi Rajbhar	Cctv camera Recoding show to client and backup given to pendrive and one cmaera survey done new cabling 15- 20 meter aprox (old need to check before then new cabling) Poe switch all port full near by																		
13-12-2024 01:25:12	Siddhesh Chavan	Systeam off issue resoved because systeam Disconnect recontct systeam and working ok in lobby																		