Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status De	etails: VE13802						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob.	9821011523						
Technician Name :	Neeraj Chauhan		Technicia	chnician Mobile : 8898885764			
Ticket Type:	Complain	Date & Time :	10-01-2025	10-01-2025 05:12:38			
Vendor Details :		-					
Company Name/Client Name :	Veena Sur Co-op Hsg	Customer's Mobile	: 982101152	23	Name :	Pratik Sir	
Address:							
Mumbai , , , , Ma	harashtra						
AMC Details :					_		
Expiry Date :	01-01-1970 05:30:00		Type:	Type:			
Product Name:	CCTV						
Complain:	1 camera need to reinstall						
Technician Comment :	Via challan no. 25647 Bake side temple camera installation done and camera angle setting camera shifting 3-4 mtr camera working okk						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	Via challan no. 25647 Bake side temple camera installation done and camera angle setting camera shifting 3-4 mtr camera working okk						
Status History :	Date Time	Technician Name	Status	Remark		Sign	
	21-01-2025 05:21:36	Neeraj Chauhan	Completed	Via challan no. 25647 Bake side temple camera installation done and camera angle setting camera shifting 3-4 mtr camera working okk		ymh	
	21-01-2025 03:25:27	Neeraj Chauhan	New			-	
	11-01-2025 04:35:25	Neeraj Chauhan	Work Pending	camera wor install.mand	reinstall done and king.4 port switch lir camera not cheking for the		
	11-01-2025 12:12:16	Neeraj Chauhan	New			-	
	10-01-2025 05:13:08	Neeraj Chauhan	New			-	

Previous Complain History :	Date Time	Technician Name	Remark	
	31-12-2024 10:18:03	Ravi Rajbhar	Cctv camera Recoding show to client and backup given to pendrive and one cmaera survey done new cabling 15-20 meter aprox (old need to check before then new cabling) Poe switch all port full near by	
	13-12-2024 01:25:12	Siddhesh Chavan	Systeam off issue resoved because systeam Disconnect recontct systeam and working ok in lobby	