Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE13448 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9320524244 **No. : Technician Name** Rahul Mhapralkar **Technician Mobile** 9168762949 : Complain 03-12-2024 12:40:43 **Ticket Type : Date & Time :** Vendor Details : Prem Shukla Barcelona Customer's Mobile 9320524244 Company Name : Name/Client Name Miraroad Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: B2 lobby front camera do not working C2 11 th floor camera offline issue resolved now working normally B2 ground floor cable Technician **Comment** : fittings on cable tie Complain Desktop - Apurva Vajaria **Operator** : **Remark** : C2 11 th floor camera offline issue resolved now working normally B2 ground floor cable fittings on cable tie **Status History : Date Time Technician Name** Status Remark Sign AR 04-12-2024 06:10:01 Rahul Mhapralkar Completed C2 11 th floor camera offline issue resolved now working normally B2 ground floor cable fittings on cable tie 04-12-2024 11:08:19 Rahul Mhapralkar New Previous **Date Time Technician Name** Remark **Complain History** 21-12-2024 Rahul Mhapralkar C1 2 floor camera installation work done it's now working 11:31:58 normally, C2 11th floor camera offline issue resolved. Access reader power supply and power point socket required Power socket 9 nos Power supply 6 nos 17-12-2024 Siddhesh Chavan C1 also Camera off issue resoved because 18 th floor poe 01:29:12 switch hang issue resoved and C2 11th floor camera off issue resoved and under observation