Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE1105 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9619151939 **No. :** Technician **Technician Mobile** 8080922981 Sachin Pawar Name : : Complain 08-02-2020 10:20:33 **Ticket Type :** Date & Time : **Vendor Details :** Taj Hotel Customer's Mobile 9619151939 **Purnanand Petwal** Company Name : Name/Client Santacruz Name : Address : Mumbai, Santacruz East, Mumbai, Maharashtra, India, , 400099, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** intrusion **Complain**: window alarms issue below mention rooms are serviced 551 439 451 644 643 351 643 -mc sensor changed.(JA111H) Technician 351 - mc removed by client bcoz window alignment is not proper so that window is fixed by **Comment** : client. Complain Desktop - Apurva Vajaria **Operator** : below mention rooms are serviced 551 439 451 644 643 351 643 -mc sensor changed.(JA111H) **Remark** : 351 - mc removed by client bcoz window alignment is not proper so that window is fixed by client. **Status History : Date Time Technician Name** Status Remark Sign 08-02-2020 SachinPawar Completed below mention rooms are serviced 07:03:02 551 439 451 644 643 351 643 -mc sensor changed.(JA111H) 351 - mc removed by client bcoz window alignment is not proper so that window is fixed by client. 08-02-2020 SachinPawar New 10:20:47 08-02-2020 SachinPawar New 10:20:34 Previous **Technician Name Date Time** Remark Complain 13-06-2023 11:07:42 Ravi Rajbhar 437 need to change small cricit with magnetic contact 446 issue **History** : resloved 445 issue resloved 22-08-2022 01:13:19 Prashant Nikalje