## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status De	etails : VE4749						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9022904145						
Technician Name :	Atique Salmani		Technicia:	Fechnician Mobile 8080922984			
Ticket Type :	Complain	Date & Time :	11-02-2022 02:54:28				
<b>Vendor Details:</b>			•				
Company Name/Client Name :	VIP PLAZA CO OPERATIVE PREMISES SOCIETY LTD	Customer's Mobile :	90229041	145	Name :	Raghu Sir	
Address:			•				
Mumbai , , , , Ma	harashtra						
AMC Details :							
Expiry Date :	12-01-2021 12:00:00		Type:		Comprehensive		
<b>Product Name:</b>	Ppm						
Complain :	CCTV						
Technician Comment :	ppm done dvr nmbr 2. 4 cameras connected only was being hang so formatted hdd and after permetion raghuji so recording on from today . and keep on under observation.						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	ppm done dvr nmbr 2. 4 cameras connected only was being hang so formatted hdd and after permetion raghuji so recording on from today . and keep on under observation.						
Status History :	Date Time	Technician Name	Status	Remark		Sign	
	12-02-2022 04:32:57	Atique Salmani	Completed	ppm done dvr nmbr 2. 4 cameras connected only was being hang so formatted hdd and after permetion raghuji so recording on from today . and keep on under observation.			
	12-02-2022 02:35:28	Atique Salmani	New	-		-	
	11-02-2022 02:54:59	Atique Salmani	New			-	
	11-02-2022 02:54:45	Atique Salmani	New			-	
	11-02-2022 02:54:28	Atique Salmani	New	I			

Previous Complain History :	Date Time Technician Name		Remark
	11-02-2022 02:54:37	Atique Salmani	terrace camera issue resolved by reconnection and working ok b302 b 204 2 camera need to changed one is pinkish and is more disturbance .
	28-01-2022 11:29:06	Ravi Rajbhar	B wing duct side cable check but office side cable & phone not found b wing busment cron weak ( crystal 48 line old version system password missing)