Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

| Service Status Details : VE10859 | | | | | | | |
|----------------------------------|---|----------------------|---------------------|--|---|------------|----------------|
| Priority: | Low | | | | | | |
| Created By: | Admin - Apurva Vajaria | | | | | | |
| Complaint Mob. | 9821919559 | | | | | | |
| Technician Name : | Neeraj Chauhan | | T: | Technician Mobile | | 8898885764 | |
| Ticket Type : | AMC visiting | Date & Time : | 1 | 13-02-2024 11:11:08 | | | |
| Vendor Details : | | | | | | | |
| Company Name/Client Name : | Tiny Tos Kindergarten School | Customer's Mobi : | ile 9 | 9821919559 | | Name: | Rahul Group |
| Address: | | | | | | | |
| Mumbai,,,, Maharashtra | | | | | | | |
| AMC Details: | | | | | | | |
| Expiry Date : | 01-01-1970 05:30:00 | | Т | Type: | | | |
| Product Name: | Ppm | | | | | | |
| Complain : | CCTV PPM need to do | | | | | | |
| Technician Comment : | Ppm done 1 camera video blur issue 1dvr CMOS battery issue. | | | | | | |
| Complain Operator : | Desktop - Apurva Vajaria | | | | | | |
| Remark: | Ppm done 1 camera video blur issue 1dvr CMOS battery issue. | | | | | | |
| Status History: | Date Time | Technician Nar | me | Status | Remark | | Sign |
| | 13-02-2024 03:30:26 | Neeraj Chauhan | | Completed | Ppm done 1 camera video blur issue 1dvr CMOS battery issue. | | Akw |
| | 13-02-2024 11:11:15 | Neeraj Chauhar | n I | New | | | - |
| Previous Complain History : | Date Time | Technician Name | | Remark CMOS battery change and dvr install but hard disk faulty hard disk handover to supriya madam | | | |
| 1115tory . | 14-02-2024 12:04:10 | Sonu Kumar | | | | | |
| | 03-10-2023 11:24:28 | Ravi Rajbhar | work powe mdm | tiny tos admin pc and pricipal pc dvr online done and ok working done and 3rd floor dvr adaptor issue then new power supply used bcz hdd not didect in dvr confrim to ekta mdm and recoding going oin in dvr and faulty adaptor hondover supriya mdm | | | |