

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13199																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9833008982																													
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																										
Ticket Type :	Complain	Date & Time :	07-11-2024 11:27:39																											
Vendor Details :																														
Company Name/Client Name :	Brijkutir Bldg	Customer's Mobile :	9833008982	Name :	Rajan Bhai																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	flat no. 152 intercom issue																													
Technician Comment :	Flat no. 152 intercom issue resolved and ok working done cable check junction to flat then connect line on instrument																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	Flat no. 152 intercom issue resolved and ok working done cable check junction to flat then connect line on instrument																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>11-11-2024 10:30:29</td><td>Ravi Rajbhar</td><td>Completed</td><td>Flat no. 152 intercom issue resolved and ok working done cable check junction to flat then connect line on instrument</td><td></td></tr><tr><td>10-11-2024 02:18:47</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>07-11-2024 06:17:14</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>Intercome cable not found work pending.</td><td></td></tr><tr><td>07-11-2024 11:27:49</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	11-11-2024 10:30:29	Ravi Rajbhar	Completed	Flat no. 152 intercom issue resolved and ok working done cable check junction to flat then connect line on instrument		10-11-2024 02:18:47	Ravi Rajbhar	New		-	07-11-2024 06:17:14	Ravi Rajbhar	Work Pending	Intercome cable not found work pending.		07-11-2024 11:27:49	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																										
11-11-2024 10:30:29	Ravi Rajbhar	Completed	Flat no. 152 intercom issue resolved and ok working done cable check junction to flat then connect line on instrument																											
10-11-2024 02:18:47	Ravi Rajbhar	New		-																										
07-11-2024 06:17:14	Ravi Rajbhar	Work Pending	Intercome cable not found work pending.																											
07-11-2024 11:27:49	Ravi Rajbhar	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>26-10-2024 11:47:10</td><td>Shiva Meena</td><td>21 intercom line ok and phone ok 31 intercom line ok home to stercech cebal folty</td></tr><tr><td>19-10-2024 12:48:30</td><td>Ravi Rajbhar</td><td>Flat no 93 intercom issue resolved and ok working done And flat no 53 cable breck one pair need to change duct to meter room 30 -35 meter approx</td></tr></tbody></table>					Date Time	Technician Name	Remark	26-10-2024 11:47:10	Shiva Meena	21 intercom line ok and phone ok 31 intercom line ok home to stercech cebal folty	19-10-2024 12:48:30	Ravi Rajbhar	Flat no 93 intercom issue resolved and ok working done And flat no 53 cable breck one pair need to change duct to meter room 30 -35 meter approx																
Date Time	Technician Name	Remark																												
26-10-2024 11:47:10	Shiva Meena	21 intercom line ok and phone ok 31 intercom line ok home to stercech cebal folty																												
19-10-2024 12:48:30	Ravi Rajbhar	Flat no 93 intercom issue resolved and ok working done And flat no 53 cable breck one pair need to change duct to meter room 30 -35 meter approx																												