







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15331																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9833008982																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	AMC visiting	Date & Time :	22-07-2025 12:05:59																						
Vendor Details :																									
Company Name/Client Name :	Brijkutir Bldg	Customer's Mobile :	9833008982	Name :	Rajan Bhai																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Ppm																								
Complain :	Intercom ppm need to do and flat no. 111/84/101 intercom issue																								
Technician Comment :	Intercom ppm done all ok working done And complaint resolve 101, 84 ,111 And inform to security and manager																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	Intercom ppm done all ok working done And complaint resolve 101, 84 ,111 And inform to security and manager																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>22-07-2025 04:51:59</td><td>Ravi Rajbhar</td><td>Completed</td><td>Intercom ppm done all ok working done And complaint resolve 101, 84 ,111 And inform to security and manager</td><td></td></tr><tr><td>22-07-2025 04:51:59</td><td>Ravi Rajbhar</td><td>Completed</td><td>Intercom ppm done all ok working done And complaint resolve 101, 84 ,111 And inform to security and manager</td><td></td></tr><tr><td>22-07-2025 12:06:04</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	22-07-2025 04:51:59	Ravi Rajbhar	Completed	Intercom ppm done all ok working done And complaint resolve 101, 84 ,111 And inform to security and manager		22-07-2025 04:51:59	Ravi Rajbhar	Completed	Intercom ppm done all ok working done And complaint resolve 101, 84 ,111 And inform to security and manager		22-07-2025 12:06:04	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
22-07-2025 04:51:59	Ravi Rajbhar	Completed	Intercom ppm done all ok working done And complaint resolve 101, 84 ,111 And inform to security and manager																						
22-07-2025 04:51:59	Ravi Rajbhar	Completed	Intercom ppm done all ok working done And complaint resolve 101, 84 ,111 And inform to security and manager																						
22-07-2025 12:06:04	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>16-07-2025 10:16:39</td><td>Atique Salmani</td><td>21 nbr new phone installed 112 issue resolved 111 cheked the cable and remooved rozer box totally rushted and also recommetion from duct side 101 more disturbance becz 2 joint in cable</td></tr><tr><td>10-07-2025 10:27:36</td><td>Prashant Paswan</td><td>44 flat intercom ok 21phone faulty 111 pending power issue</td></tr></tbody></table>					Date Time	Technician Name	Remark	16-07-2025 10:16:39	Atique Salmani	21 nbr new phone installed 112 issue resolved 111 cheked the cable and remooved rozer box totally rushted and also recommetion from duct side 101 more disturbance becz 2 joint in cable	10-07-2025 10:27:36	Prashant Paswan	44 flat intercom ok 21phone faulty 111 pending power issue											
Date Time	Technician Name	Remark																							
16-07-2025 10:16:39	Atique Salmani	21 nbr new phone installed 112 issue resolved 111 cheked the cable and remooved rozer box totally rushted and also recommetion from duct side 101 more disturbance becz 2 joint in cable																							
10-07-2025 10:27:36	Prashant Paswan	44 flat intercom ok 21phone faulty 111 pending power issue																							