Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE5905							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9833008982						
Technician Name	Ravi Rajbhar		Technician	n Mobile : 8080922965			
Ticket Type :	Complain	Date & Time :	08-07-2022 10:08:50				
Vendor Details :							
Company Name/Client Name :	Brijkutir Bldg	Customer's Mobile :	983300898	32	Name :	Rajan Bhai	
Address:							
Mumbai,,,, Maharashtra							
AMC Details :							
Expiry Date :	01-01-1970 05:30:	Type:					
Product Name:	Intercom						
Complain:	Flat no 91/84 and security back side and front side gate intercom issue						
Technician Comment :	flat no 91 ,84, 152, intercom issue resolved and ok working done main gate issue resolved ,and back side security cabin line ok instrument issue $\frac{1}{2}$						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	flat no 91 ,84, 152, intercom issue resolved and ok working done main gate issue resolved ,and back side security cabin line ok instrument issue $\frac{1}{2}$						
Status History:	Date Time	Technician Name	Status	Remark		Sign	
	08-07-2022 12:43:10	Ravi Rajbhar	Completed	flat no 91 ,84, 152, intercom issue resolved and ok working done main gate issue resolved ,and back side security cabin line ok instrument issue		Som	
	08-07-2022 10:09:05	3	New			-	
	08-07-2022 10:08:50	Ravi Rajbhar	New			-	
Previous Complain History :	Date Time	Technician Name	Remark				
	06-07-2022 10:00:51	Ravi Rajbhar	801 , 601 , main gate security cabin 99, back side security table 91 and 92 line ok instrument issue				
	15-03-2022 10:28:33	15-03-2022 10:28:33 YogeshDesai flat no 131 flat to duct cable not traceable cable cannnot be fined. flat no 82 flat no connection point for phone to install					